



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
NGO MIN YING	Cust No/Name / NGO MIN YING
24 MOONBEAM VIEW	Reg No/Reg Date SMR4084H / 03/01/202
SINGAPORE 277278	Date In/Mileage / 0
Contact No Mobile: 91546268	Chassis No JMAXTGK1WKZ001917
	Engine No 4B40GY7479
	Make/Model MIT/ECLIPSE CROSS 1.5 STYLE SR (T23
	Colour/Trim CO2 BRONZE METALLIC/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	07/05/2022/ 11:15	TLK	282 / Kevin Leong	23083			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1280.00
REPLACE FRONT BUMPER PANEL & AFFECTED AREA					640 x 1			1280.00
E PNT98000								1100.00
PAINT WORK ON FRONT BUMPER PANEL					550 x 1			1100.00
E PNT88000								180.00
REMOVE & INSTALL FRONT PARKING ASSIST FOR FACILITATE REPAIR								180.00
M SUNDRY								100.00
TO APPLY SEALANT ON AFFECTED AREA								100.00
M SUNDRY								50.00
PERFORM RUST PREVENTION								50.00
A 54900099								80.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								80.00
A 10028901								280.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								280.00
M SUNDRY								50.00
TO SUPPLY FRT NUMBER PLATE WITH FRAME								50.00
M SUNDRY								50.00
SUNDRIES					1.00	990.00	00.00	990.00
M FACE, FR BUMPER	CRH				1.00	382.00	00.00	382.00
M COVER, FR BUMPER	CUT (BLACK) (CRH) - BR				1.00	295.00	00.00	295.00
M GARNISH, FR BUMPER SIDE	CRH				1.00	295.00	00.00	295.00
M EXTENSION, FR BUMPER	NEC (Spoiler centre front)				1.00	318.00	00.00	318.00
M BRKT, F/BMPR T/SIG LAMP, RH					1.00	17.00	00.00	17.00
M BRACKET, FR BUMPER SIDE, RH					1.00	25.00	00.00	25.00

Steve (LKK)

9/6/22, 1.02pm

W PL

P/P

by PL

3 days

Steve (LKK)
9/6/22, 1.00pmM PL
P/P
by ALG
3 days

KKK Auto Consultants hence notify

Confirm & accepted by:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and

Authorized signatory and company stamp

7% GST on


Nett 5,197.00

363.79

Total Payable 5,560.79

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

INSURANCE CO. : **INDIA**

Supplementary For Registration No.: **SMR 4084 H**

				<u>Cost (\$)</u>
<u>Materials</u>				
1	Headlamp Assy, RH	BR		2,498.00 ✓
			7% Gst	174.86
			Total	<u>2,672.86</u>

Thank You.

Yours faithfully

CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

LARRY SONGCUAN
CUSTOMER SERVICE

TEL: 6568 4658

FAX : 6567 5258