

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

Xiao Tony

Estimate No: EST2200151
Date: 13 May 2022

ATTN: Motor Claim Department

Veh Reg No: SLE9520M
Make/Model: KIA CERATO FORTE
1.6SX AT SBS D/AB
2WD 4DR
Chasis No: KNAFW411MA5274862
Reg. Date: 14/09/2010
Your Ref No: SHC8086P

Claim Type: Third Party
Accident Date: 11/05/2022
TP Veh Reg No: SHC8086P

Estimate Repair Cost to Vehicle No :SLE9520M

Quantity	Description	List Price S\$	Amount S\$
	List Price		
1	1 PC BONNET <i>Distorted</i>	✓ 1,056.00 ✓	
2	2 PCS BONNET HINGE <i>Bent</i>	✓ 132.00 ✓	
3	1 PC BONNET RUBBER LONG <i>green</i>	31.40 +	
4	1 PC BONNET RUBBER SHORT	29.60 +	
5	1 PC BONNET LOCK <i>new</i>	✓ 146.70 ✓	
6	1 PC FRT FENDER RH <i>Distorted</i>	✓ 460.80 ✓	
7	1 PC FRT WHEEL HOUSING RH <i>Distorted</i>	966.20 ✓	798
8	1 PC FRT SUPPORT PANEL <i>crushed</i>	627.10 ✓	
9	1 PC FRT GRILLE <i>crushed</i>	285.10 ✓	
10	1 PC FRT GRILLE EMBLEM <i>new</i>	✓ 50.20 ✓	
11	1 PC HEADLAMP RH <i>crushed</i>	✓ 743.80 ✓	
12	1 PC HEADLAMP LH	✓ 743.80 ✓	
13	1 PC FRT BUMPER <i>Distorted</i>	✓ 784.80 ✓	
14	1 PC FRT BUMPER REINFORCEMENT <i>new</i>	294.40 *	
15	2 PCS FRT BUMPER SIDE RETAINER <i>new</i>	✓ 78.20 ✓	
16	1 PC FRT BUMPER SPONGE <i>crushed</i>	✓ 101.80 ✓	
17	1 PC FRT FOG LAMP RH <i>crushed</i>	✓ 277.10 ✓	
18	1 PC FRT FOG LAMP COVER RH <i>Distorted</i>	✓ 99.60 ✓	
19	1 PC FRT FOG LAMP LH <i>green</i>	277.60 +	
20	1 PC FRT FOG LAMP COVER LH	99.60 +	
21	1 PC FRT BUMPER GRILLE <i>new</i>	166.20 +	
22	1 PC FRT BUMPER LOWER SPOILER <i>Distorted</i>	✓ 281.70 ✓	
23	1 PC FRT NUMBER PLATE BASE <i>crushed</i>	✓ 78.40 ✓	
24	1 PC FRT WINDSCREEN GLASS <i>crushed</i>	✓ 1,231.40 ✓	
25	1 PC FRT WINDSCREEN MOULDING <i>new</i>	✓ 99.40 ✓	
26	1 PC FRT WIPER PANEL GARNISH <i>crushed</i>	✓ 187.00 ✓	
27	1 PC FRT WIPER PANEL GARNISH RUBBER <i>new</i>	54.40 +	
28	1 PC FRT WIPER PANEL RH CORNER GARNISH <i>Distorted</i>	38.60 ✓	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 11/05/2022
TP Veh Reg No: SHC8086P

Estimate No: EST2200151
Date: 13 May 2022

Veh Reg No: SLE9520M
Make/Model: KIA CERATO FORTE
1.6SX AT SBS D/AB
2WD 4DR
Chasis No: KNAFW411MA5274862
Reg. Date: 14/09/2010
Your Ref No: SHC8086P

Estimate Repair Cost to Vehicle No :SLE9520M

Quantity	Description	List Price	Amount
		SS	SS
29	1 PC FRT FENDER LH <i>Buchel</i>	460.80 <i>x</i>	✓
30	1 PC FRT FENDER COWLING LH <i>from new</i>	169.30 <i>x</i>	✓
31	1 PC FRT DOOR RH <i>Dented</i>	872.20	✓
32	1 PC FRT DOOR SIDE MIRROR RH <i>Dented</i>	468.60	✓
33	1 PC FRT DOOR RH FRAME BLACK STICKER <i>new</i>	39.50	✓
34	1 PC FRT DOOR OUTER HANDLE RH <i>new</i>	101.80 <i>x</i>	✓
35	1 PC FRT SHOCK ABSORBER RH <i>Distorted</i>	358.50	✓
36	1 PC FRT LOWER ARM RH	391.80	✓
37	1 PC FRT KNUCKLE ARM RH <i>2pc</i>	385.00	✓
38	1 PC FRT BEARING RH <i>2pc</i>	85.40	✓
39	1 PC FRT WHEEL HUB RH <i>Dented</i>	232.00	✓
40	1 PC FRT RH BRAKE DISC ROTOR <i>2nd</i>	312.40	✓
41	1 PC FRT RH BRAKE DISC ROTOR PANEL <i>Bent</i>	112.80	✓
42	1 PC FRT BRAKE PIPE RH <i>cut</i>	68.10	✓
43	1 PC FRT RH BRAKE CALIPER <i>new</i>	566.90 <i>x</i>	✓
44	1 PC ANTI ROLL BAR <i>Bent</i>	280.00	✓
45	1 PC ANTI ROLL BAR LINKAGE <i>Bent</i>	91.40	✓
46	1 PC FRT DRIVE SHAFT RH <i>2pc</i>	1,086.80	✓
47	1 PC FRT CROSSMEMBER <i>Bent</i>	1,271.60	✓
48	1 PC STEERING RACK & PINION <i>Bent</i>	2,263.70	✓
49	1 PC ENGINE MOUNTING RH <i>Band.</i>	239.80	✓
50	1 PC FRT ENGINE MOUNTING RH BRACKET <i>crushed</i>	133.90	✓
51	1 PC POWER STEERING FLUID TANK <i>crushed</i>	176.00	✓
52	1 PC POWER STEERING FLUID TANK PIPE <i>new</i>	91.40 <i>x</i>	✓
53	1 PC FRT POWER STEERING PUMP <i>new</i>	754.60 <i>x</i>	✓
54	1 PC ENGINE MOUNTING LH <i>2pc</i>	269.70 <i>x</i>	✓
55	1 PC ENGINE MOUNTING LH BRACKET <i>2pc</i>	138.70 <i>x</i>	✓
56	1 PC FRT LOWER ARM TIE ROD <i>Bent</i>	81.20	✓
57	1 PC POWER STEERING PIPE <i>new</i>	122.30 <i>x</i>	✓

1956

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 11/05/2022
TP Veh Reg No: SHC8086P

Estimate No: EST2200151

Date: 13 May 2022

Veh Reg No: SLE9520M

Make/Model: KIA CERATO FORTE
1.6SX AT SBS D/AB
2WD 4DR

Chasis No: KNAFW411MA5274862

Reg. Date: 14/09/2010

Your Ref No: SHC8086P

Estimate Repair Cost to Vehicle No :SLE9520M

Quantity	Description	List Price	Amount
		SS	SS
58	1 PC RADIATOR <i>new</i>	19501.30 701.80 <i>+</i>	
59	1 PC FRT WIPER TANK <i>Distorted</i>	17551.17 177.60 <i>✓</i>	
60	1 PC FRT WIPER TANK MOTOR <i>2nd</i>	100.40 <i>✓</i>	
61	1 PC AIRCON CONDENSER <i>wrapped</i>	773.30 <i>✓</i>	
62	1 PC FRT AIRCON DISCHARGE PIPE <i>At the But</i>	299.90 <i>✓</i>	
63	1 PC AIRCON RECEIVER PIPE <i>At the But</i>	243.50 <i>✓</i>	
	<i>1pc air con compressor pipe. But</i>	23,345.60	
	<i>1pc front fan belt 201.60 ✓</i>	4,669.12	18,676.48
	<i>Special Net Tensioner 299.70 ✓</i>		
64	1 SET FRT FENDER COWLING CLIPS RH <i>new</i>	60.00 30 <i>-</i>	
65	1 SET FRT GRILLE CLIPS <i>new</i>	40.00 20 <i>-</i>	
66	1 SET FRT BUMPER GRILLE CLIPS <i>new</i>	40.00 <i>+</i>	
67	1 SET FRT BUMPER LOWER SPOILER CLIP <i>new</i>	40.00 20 <i>-</i>	
68	1 PC FRT NUMBER PLATE <i>new</i>	50.00 <i>+</i>	
69	1 PC FRT WINDSCREEN GUM <i>new</i>	60.00 30 <i>-</i>	
70	1 PC FRT WINDSCREEN SEAL <i>new</i>	60.00 30 <i>-</i>	
71	1 SET FRT FENDER COWLING CLIPS LH <i>new</i>	40.00 <i>+</i>	
72	1 PC FRT SPORTS RIM RH <i>Cracked</i>	800.00 400 <i>-</i>	
73	1 PC FRT TYRE RH <i>Punctured</i>	300.00 180 <i>-</i>	
74	1 PC POWER STEERING OIL <i>new</i>	80.00 40 <i>-</i>	
		1,570.00	1,570.00
	Labour		
75	1 TO CHECK WIRING	50.00 30 <i>-</i>	
76	1 TO REFILL AIRCON GAS	120.00 100 <i>-</i>	
77	1 TO REMOVE AND REFIT FRONT WINDSCREEN	120.00 <i>✓</i>	
78	1 PC TO REMOVE AND REFIT RH DOOR GLASS	100.00 50 <i>-</i>	
79	1 TO REMOVE AND REFIT ENGINE	800.00 300 <i>-</i>	
80	1 TO REMOVE AND REFIT UNDERCARRIAGE	580.00 500 <i>-</i>	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 11/05/2022
TP Veh Reg No: SHC8086P

Estimate No: EST2200151

Date: 13 May 2022

Veh Reg No: SLE9520M

Make/Model: KIA CERATO FORTE
1.6SX AT SBS D/AB
2WD 4DR

Chasis No: KNAFW411MA5274862

Reg. Date: 14/09/2010

Your Ref No: SHC8086P

Estimate Repair Cost to Vehicle No :SLE9520M

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
81	1 TO CHECK WHEEL ALIGNMENT	120.00	80.
82	1 TO SPRAY PANEL SEALANT	150.00	80.
83	1 (FRONT) TO SPRAY PAINTING	2,000.00	1400.
84	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	2,800.00	1600
		6,840.00	6,840.00
	Total		S\$ 27,086.48
	Add GST @ 7%		1,896.05
	Total Amount Payable		<u>S\$ 28,982.53</u>

TOTAL: SINGAPORE DOLLAR TWENTY EIGHT THOUSAND NINE HUNDRED EIGHTY TWO AND CENTS FIFTY THREE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 22861.17
A/S: 18K 1/5 13/05/22.

17 Paps

18K

17 Paps