

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

*TR AXA
 Cecilia*

TAX INVOICE

NG HEOK KWEE
 49 MACKERROW ROAD
 SINGAPORE 358616

Repair Code : CLM17202

Date in : 06/05/2022

Vehicle Num. : SCL2828S

Model : MERCEDES BENZ E250 SEDAN (R18)

Chassis/Eng# : WDD2120362A800362/27492030061182

Contact : 97363800

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID '7G-TRONIC' EMBLEM	1	98.00	98.00 +
REAR BOOTLID 'E250' EMBLEM	1	75.00	75.00 +
REAR BOOTLID 'LOGO' EMBLEM	1	60.00	60.00 +
REAR BOOTLID 'LOGO' EMBLEM CLIPS	3	6.50	19.50 +
REAR BOOTLID WEATHER STRIP SEAL	1	238.00	238.00 +
REAR BUMPER <i>Dehd</i>	1	1381.00	1,381.00 ✓
REAR BUMPER CENTER CHROME MOULDING <i>per</i>	1	178.00	178.00 ✓
REAR BUMPER CHROME MOULDING L/R <i>per</i>	2	145.00	290.00 ✓
REAR BUMPER LOWER BRACKET L/R <i>per RH only</i>	2	75.00	150.00 ⁷⁵ ✓
REAR BUMPER LOWER DIFFUSER <i>Dehd</i>	1	480.00	480.00 ✓
REAR BUMPER REINFORCEMENT <i>Dented</i>	1	670.00	670.00 ✓
REAR BUMPER REVERSE SENSOR <i>1 piece dented</i>	4	234.00	936.00 ²³⁴ ✓
REAR BUMPER REVERSE SENSOR HOLDER <i>per</i>	6	25.00	150.00 ²⁵ ✓
REAR BUMPER REVERSE SENSOR RUBBER SEAL <i>per</i>	4	6.00	24.00 ✓
REAR BUMPER REVERSE SENSOR WIRE HARNESS - SET <i>per</i>	1	122.00	122.00 +
REAR BUMPER SIDE RETAINER L/R <i>per</i>	2	31.00	62.00 +
REAR BUMPER TOP RETAINER <i>could</i>	1	210.00	210.00 ✓
REAR BUMPER TOW HOOK COVER <i>Dehd</i>	1	79.00	79.00 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

NG HEOK KWEE
 49 MACKERROW ROAD
 SINGAPORE 358616

Contact : 97363800

TAX INVOICE

Repair Code : CLM17202
 Date in : 06/05/2022
 Vehicle Num. : SCL2828S
 Model : MERCEDES BENZ E250 SEDAN (R18)
 Chassis/Eng# : WDD2120362A800362/27492030061182

REAR END PANEL <i>Reps</i>	1	752.00	752.00	<i>+</i>
REAR END PANEL INNER TOP GARNISH <i>Rehd</i>	1	156.00	156.00	<i>✓</i>
REAR EXHAUST RH CHROME TAIL PIPE <i>Dented</i>	1	345.00	345.00	<i>✓</i>
REAR EXHAUST RH CHROME TAIL PIPE BRACKET <i>cracked</i>	1	52.00	52.00	<i>✓</i>
REAR RH SIDE ALUMINIUM HEAT SHIELD <i>neu</i>	1	330.00	330.00	<i>+</i>
REAR TAILLAMP CLIPS L/R <i>neu</i>	4	6.50	26.00	<i>13</i>
REAR TAILLAMP L/R <i>RH cracked</i>	2	585.00	1,170.00	<i>585</i>
REAR TAILLAMP LOWER BRACKET L/R <i>neu</i>	2	73.00	146.00	<i>+</i>
Subtotal before discount			8,199.50	
Percentage discount 10%			819.95	
Sub-total 1			7,379.55	
FRONT SEAT HEADREST L/R <i>Adjusted</i>	2	880.00	1,760.00	<i>1200</i>
REAR BOOTLID 'C&C' EMBLEM <i>neu</i>	1	60.00	60.00	<i>+</i>
REAR BUMPER CLIPS - SET <i>neu</i>	1	50.00	50.00	<i>30</i>
REAR BUMPER RIVET - SET <i>neu</i>	1	100.00	100.00	<i>50</i>
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>neu</i>	1	50.00	50.00	<i>10</i>

*** This is a computer-generated document which requires no signature.***

*Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

NG HEOK KWEE
 49 MACKERROW ROAD
 SINGAPORE 358616

TAX INVOICE

Repair Code : CLM17202
 Date in : 06/05/2022
 Vehicle Num. : SCL2828S
 Model : MERCEDES BENZ E250 SEDAN (R18)
 Chassis/Eng# : WDD2120362A800362/27492030061182

Contact : 97363800

Subtotal before discount	2,020.00
Percentage discount 0%	0.00
Sub-total 2	2,020.00
Parts-total	9,399.55

LABOUR

To reset system after repair works	250.00	150
To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	60.00	
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	140.00	60
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,300.00	500
To remove and reinstall exhaust pipe.	80.00	+
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,100.00	400
To apply anti-rust chemical on repaired and replaced panel.	50.00	
Labour Total	2,980.00	
Parts & Labour Total	12,379.55	

1320

*** This is a computer-generated document which requires no signature.***

Adnan Lj
 L/S 18/05/22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

total: 6927.30
 L/S: S.S.K.
 06 Days
 S.S.K.
 06 Days