

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0379/2022/JT
DATE : 12-May-22
WIP : 23775

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 18/5/22

YOUR INSURED VEH NO : GBC 332 C

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LOW SIEW HON
ADDRESS : 2C LIMAU GARDEN
SINGAPORE 467861
TELEPHONE : HP +65 93897013
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : MT/00656746/02
VEHICLE NO : **SKU 2793 R**
MODEL CODE : AUDI Q3 1.4 TFSI S TRONIC
MODEL YEAR : 15/7/2015
ENGINE NO : CZD 206628
CHASSIS NO : WAUZZZ8UFR048639
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-May-22
PLACE OF ACCIDENT : ALONG PIE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKU 2793 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$ 280.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,600.00	
3	TO RESPRAY REAR BUMPER, REAR BUMPER LOWER SPOILER, REAR LID, REAR END PANELLING AND BOTH REAR WHEEL ARCH TRIMS.	\$ 4,500.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 6,572.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKU 2793 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 1,682.00	
2	REAR BUMPER FIXING PARTS	1	\$ 129.00	
3	REAR BUMPER SPOILER	1	\$ 979.00	
4	REAR BUMPER DIFUSSER	1	\$ 786.00	
5	REAR BUMPER TOWING EYE - LH	1	\$ 48.00	
6	REAR BUMPER TAIL LIGHT - LH	1	\$ 512.00	
7	REAR BUMPER REINFORCEMENT BEAM	1	\$ 693.00	
8	REAR BUMPER GUIDE SECTION - LH	1	\$ 112.00	
9	REAR PARKING AID SENSOR	2	TBC	
10	REAR PARKING AID SENSOR SEAL RING	4	\$ 6.00	
11	REAR PACKING ADHESIVE	1	\$ 21.00	
12	AUDI EMBLEM	1	\$ 144.00	
13	Q3 EMBLEM	1	\$ 104.00	
14	TFSI EMBLEM	1	\$ 104.00	
15	REAR WHEEL ARCH COVER - LH / RH	2	\$ 1,114.00	
16	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 6,734.00	
TOTAL LABOUR CHARGES		:	\$ 6,572.00	
GRAND TOTAL		:	\$ 13,306.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT