



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2206991

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 10/11/2022
Reference CC4/LPC22004542/Apa3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SNE 3674T
Insured Veh. XE 1513U
Claim No. 22/22/22/VC05/025766
Policy No. Z22VC05010538
Accident Date 06/05/2022
Inspection Date 11/05/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC22004542/Apa3q2 Date: 10/11/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 1513U	Veh. Inspected	SNE 3674T	
Policy No.	Z22VC05010538	Coverage (\$)	0.00	
Claim No.	22/22/22/VC05/025766	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	09/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2022	
Chassis No.	RV51013908	Colour	BLACK	
Odometer	11767 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	HANKOOK	6 mm	
L/H Front Tyre	215/60 R16	HANKOOK	6 mm	
R/H Rear Tyre	215/60 R16	HANKOOK	6 mm	
L/H Rear Tyre	215/60 R16	HANKOOK	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/05/2022	Inspection Date	11/05/2022	
Survey held at	MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNE 3674T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR DOOR RH	DENTED	1,458.00	1,205.00
1	REAR DOOR TAPE RH	NECESSARY	30.10	30.10
1	REAR DOOR PROTECTOR RH	NOT NECESSARY	412.00	-
1	REAR DOOR LOWER SEAL RH	NOT NECESSARY	51.90	-
1	REAR DOOR SIDE GARNISH RH	CUT	259.00	259.00
1	REAR DOOR POWER WINDOW MOTOR RH	NOT NECESSARY	541.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	615.20	-
1	REAR FENDER COWLING RH	DEFORMED	251.00	251.00
1	REAR WHEEL ARCH PROTECTOR RH	TORN	452.00	452.00
1	REAR BUMPER	DEFORMED	863.50	863.50
1	REAR BUMPER LOWER	CUT	511.00	395.00
1	REAR AXLE	NOT NECESSARY	2,110.00	-
1	REAR SHOCK ABSORBER RH	DAMAGED	412.00	412.00
1	REAR WHEEL BEARING	DAMAGED	212.00	212.00
	LESS 20% DISCOUNT		-1,635.74	-815.92
			6,542.96	3,263.68
<u>SPECIAL NETT ITEMS</u>				
10	REAR BUMPER CLIPS @\$6.50 (SN)	NECESSARY	65.00	30.00
1	REAR TYRE RH (SN)	PUNCTURE	300.00	200.00
1	REAR SPORTS RIM RH (SN)	CUT	800.00	580.00
15	REAR FENDER INNER COWLING CLIP @\$6.50(SN)	NECESSARY	97.50	30.00
12	REAR FENDER INNER TRIM CLIPS @\$6.50(SN)	NOT NECESSARY	78.00	-
10	REAR WHEEL ARCH GARNISH CLIP @\$6.50(SN)	NECESSARY	65.00	20.00
			1,405.50	860.00
<u>LABOUR</u>				
	TO PANEL BEAT ,REMOVE AND REPLACE PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER RH .		600.00	400.00
	TO SPRAY PAINT AFFECTED AREA.		800.00	600.00
	CONDUCT WHEEL ALIGNMENT.		80.00	80.00

Report Ref No. CC4/LPC22004542/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING CHECK.		80.00	30.00
	REMOVE AND REFIR REAR UNDERCARRIAGE.		400.00	100.00
			1,960.00	1,210.00
GRAND TOTAL			9,908.46	5,333.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,250.00

Report Ref No. CC4/LPC22004542/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNE 3674T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNE 3674T

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

