

MY CAR CONSULTANT PTE LTD
(Co Reg. No. 201605878Z)
60 JALAN LAM HUAT, CARROS CENTRE
#05-68 (S737869)
Tel: 98888885

TO	: LONPAC	DATE	10-May-22
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	T/P CLAIM
<i>Civilian.</i>		VEHICLE DETAILS	
		VEHICLE NO	: SNE3674T
		MODEL	: HONDA VEZEL

QUOTATION SUMMARY

RV51013908

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR DOOR RH <i>Dented</i>	1	\$ 1,458.00	\$ 1,458.00
2	REAR DOOR TAPE RH <i>new</i>	1	\$ 30.10	\$ 30.10
3	REAR DOOR PROTECTOR RH <i>new</i>	1	\$ 412.00	\$ 412.00
4	REAR DOOR LOWER SEAL RH <i>new</i>	1	\$ 51.90	\$ 51.90
5	REAR DOOR SIDE GARNISH RH <i>lt</i>	1	\$ 259.00	\$ 259.00
6	REAR DOOR POWER WINDOW MOTOR RH <i>new</i>	1	\$ 541.00	\$ 541.00
7	REAR FENDER RH <i>Regis</i>	1	\$ 615.20	\$ 615.20
8	REAR FENDER COWLING RH <i>Dented</i>	1	\$ 251.00	\$ 251.00
9	REAR WHEEL ARCH PROTECTOR RH <i>torn</i>	1	\$ 452.00	\$ 452.00
10	REAR BUMPER <i>damaged</i>	1	\$ 863.50	\$ 863.50
11	REAR BUMPER LOWER <i>lt</i>	1	\$ 511.00	\$ 511.00
12	REAR AXLE <i>new</i>	1	\$ 2,110.00	\$ 2,110.00
13	REAR SHOCK ABSORBER RH <i>Byd</i>	1	\$ 412.00	\$ 412.00
14	REAR WHEEL BEARING <i>Byd</i>	1	\$ 212.00	\$ 212.00

4079.60
Wm 20% : 3263.68

TOTAL PRICE	\$8,178.70
LESS 20%	\$1,635.74
SUB TOTAL PRICE	\$6,542.96

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS <i>new</i>	10	\$ 6.50	\$ 65.00
2	REAR TYRE RH <i>Punctured</i>	1	\$ 300.00	\$ 300.00
3	REAR SORTS RIM RH <i>lt</i>	1	\$ 800.00	\$ 800.00
4	REAR FENDER INNER COWLING CLIP <i>new</i>	15	\$ 6.50	\$ 97.50
5	REAR FENDER INNER TRIM CLIPS <i>new</i>	12	\$ 6.50	\$ 78.00
6	REAR WHEEL ARCH GARNISH CLIP <i>new</i>	10	\$ 6.50	\$ 65.00

860

TOTAL

\$1,405.50

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$600.00	400	
2	TO SPRAY PAINT AFFECTED AREA	\$800.00	600	
3	CONDUCT WHEEL ALIGNMENT	\$80.00	✓	
4	WIRING CHECK	\$80.00	30	
5	REMOVE AND REPAIR REAR UNDERCARRIAGE	\$400.00	100	

TOTAL

\$1,960.00

1210

ESTIMATE REPORT

TOTAL PARTS COST : \$7,948.46
 TOTAL LABOUR COST : \$1,960.00
 TOTAL REPAIR COST : \$9,908.46

Adrian L
 L/S 11/05/22.
 65 Days.

total: 5333.68

L/S: 4250

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: