

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004543/KPA3Q2**Date:** 26/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210014491
Claimant Vehicle No :	GBB9119Z	Insured Vehicle No :	GBF8585X
Date of Loss:	12/05/2022	Nature of Claim:	TP
		Claim No:	4428636731SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB9119Z		
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Engine No:	1KDB015501
Reg. Date:	15/01/2020 (Man. Year: 2019)	Chassis No:	JTFAT35Y30K214651
Colour:	Yellow	Odometer:	101864 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Michelin 4 mm	Rear Left Side:	Falken 2/2 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Falken 2/2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,154.61	3,924.54	230.07	5.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,070.00	2,480.00	590.00	19.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,224.61	6,404.54	820.07	11.35
Approved Total (Overridden) (S\$)		5,100.00		
(S\$)	7,224.61	5,100.00	2,124.61	29.41
+ GST 7.00/7.00% (S\$)	505.72	357.00	148.72	29.41
Nett Amount (S\$)	7,730.33	5,457.00	2,273.33	29.41
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,959.00		

INSPECTION

Date of Assignment:	13/05/2022	
Date Inspected:	13/05/2022	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE	Dented / Distorted	643.85 FL	*643.85 FL
2	1		*FRONT GRILLE LOGO	Necessary	74.40 FL	*74.40 FL
3	4		*FRONT GRILLE CLIPS	Necessary	18.00 FL	*18.00 FL
4	1		*LH HEADLAMP	Cut	969.20 FL	*969.20 FL
5	1		*FRONT LH CORNAL PANEL	Mtg Cracked	356.70 FL	*356.70 FL
6	1		*FRONT PANEL	Bent	1,156.70 FL	*1,156.70 FL
7	1		*FRONT LH SIDE MIRROR	Dented / Cut	636.40 FL	*636.40 FL
8	1		*FRONT LH SIDE MIRROR MOTOR	Mtg Cracked	666.90 FL	*666.90 FL
9	1		*FRONT WINDSCREEN GLASS RUBBER	Serviceable	280.10 FL	*- FL
10	1		*FRONT BUMPER	Buckled	683.90 FL	*683.90 FL
11	1		*FRONT LH DOOR COY STICKER	Necessary	20.00 FS	*20.00 FS
12	1		*FRONT NUMBER PLATE	Serviceable	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,526.15	5,226.05
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,371.54	1,301.51
Total Parts (\$\$)	4,154.61	3,924.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX FRONT WINDSCREEN GLASS	New	60.00	60.00
2	REMOVE & REFIX DASHBOARD ,METER ASSY AND CHECK WIRING	New	230.00	220.00
3	REMOVE AND REFIX AIRCON CHECK ,VACUUM & REFILL GAS	New	100.00	100.00
4	REMOVE & REFIX FRT BUMPER ASSY ,GRILLE ,HEADLAMPS,SIDE MIRROR ,TO CUT ,WELD & RENEW FRT PANEL AND REALIGN THE SAME	New	780.00	700.00
5	PUTTY & RESPRAY ON FRT GRILLE ,FRT PANEL ,FRT WIPER PANEL ,FRT BUMPER ,FRT LH DOOR	New	1,000.00	800.00
6	TO REWRITE ADVERTISEMENT	New	900.00	600.00
Gross Labour Cost (\$\$)			3,070.00	2,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >