

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 09/05/2022
TP Veh Reg No: SLG8366M

Estimate No: EST2200148
Date: 11 May 2022
Veh Reg No: SKA5715C
Make/Model: HONDA JAZZ 1.3L A
Chasis No: JHMGE68509S235457
Reg. Date: 15/03/2011
Your Ref No: SLG8366M

Estimate Repair Cost to Vehicle No :SKA5715C

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
List Price			
1	1 PC BOOT LID	844.10	
2	2 PCS BOOT LID HINGE	124.00	
3	1 PC BOOT LID "JAZZ" EMBLEM	48.80	
4	1 PC BOOT LID LOGO	50.20	
5	1 PC BOOT LID LOCK	189.50	
6	1 PC BOOT LID LOCK CHECKER	38.90	
7	1 PC BOOT LID TRIM	177.20	
8	1 PC BOOT LID RUBBER	182.40	
9	2 PCS REAR NUMBER PLATE LAMP	124.80	
10	1 PC REAR WINDSCREEN RUBBER	120.50	
11	1 PC REAR FENDER LH	786.90	
12	1 PC REAR FENDER TRIM LH	286.50	
13	1 PC REAR FENDER TRIM RH	286.50	
14	1 PC REAR PANEL	496.50	
15	1 PC REAR PANEL TRIM	166.80	
16	1 PC SPARE TYRE PANEL	737.00	
17	1 PC SPARE TYRE PANEL SPONGE	236.80	
18	1 PC REAR SPARE TYRE HARDBOARD	289.60	
19	1 PC TAIL LAMP LH	366.40	
20	1 PC TAIL LAMP - RH	366.40	
21	1 PC REAR BUMPER	497.70	
22	2 PCS REAR BUMPER SIDE RETAINER	93.60	
		6,511.10	
		Less 20%	1,302.22
			5,208.88
Special Net			
23	1 SET BOOTLID TRIM CLIPS	60.00	
24	1 PC REAR NUMBER PLATE	50.00	
25	1 PC REAR WINDSCREEN SEAL	60.00	
26	1 PC REAR WINDSCREEN SEALANT	60.00	
27	1 PC REVERSE CAMERA	480.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 09/05/2022
TP Veh Reg No: SLG8366M

Estimate No: EST2200148
Date: 11 May 2022
Veh Reg No: SKA5715C
Make/Model: HONDA JAZZ 1.3L A
Chasis No: JHMGE68509S235457
Reg. Date: 15/03/2011
Your Ref No: SLG8366M

Estimate Repair Cost to Vehicle No :SKA5715C

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
28	1 SET REAR FENDER TRIM CLIPS LH	60.00	
29	1 SET REAR FENDER TRIM CLIPS RH	60.00	
30	1 PC REAR FENDER LH SIDE GLASS SEAL	60.00	
31	1 PC REAR FENDER LH SIDE GLASS SEALANT	60.00	
32	1 SET REAR PANEL TRIM CLIPS	30.00	
33	1 PC REAR BUMPER LOWER SPOILER	600.00	
34	1 SET REAR BUMPER CLIPS	40.00	
		1,620.00	1,620.00
	Labour		
35	1 TO CHECK WIRING	50.00	
36	1 TO REMOVE AND REFIT REAR BOOTLID SPOILER	80.00	
37	1 TO REMOVE AND REFIT THIRD BRAKE LIGHT	80.00	
38	1 TO REMOVE AND REFIT REAR VIEW CAMERA	80.00	
39	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00	
40	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	
41	1 TO REMOVE AND REFIT REAR INNER TRIM	120.00	
42	1 TO REMOVE AND REFIT PETROL TANK	150.00	
43	1 TO REMOVE AND REFIT LH FENDER SIDE GLASS	120.00	
44	1 TO SPRAY UNDERSEAL	140.00	
45	1 TO REMOVE AND REFIT SEAT CUSHION	200.00	
46	1 (REAR) TO SPRAY PAINTING	1,500.00	
47	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,600.00	
		4,320.00	4,320.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 09/05/2022
TP Veh Reg No: SLG8366M

Estimate No: EST2200148
Date: 11 May 2022
Veh Reg No: SKA5715C
Make/Model: HONDA JAZZ 1.3L A
Chasis No: JHMGE68509S235457
Reg. Date: 15/03/2011
Your Ref No: SLG8366M

Estimate Repair Cost to Vehicle No :SKA5715C

Quantity	Description	List Price	Amount
		S\$	S\$
	Total		S\$ 11,148.88
	Add GST @ 7%		780.42
	Total Amount Payable		S\$ 11,929.30

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND NINE HUNDRED TWENTY NINE AND CENTS THIRTY ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE