

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16

AIG BUILDING, SINGAPORE 079120

TEL: 64193000

FAX: 68357416

ATTN: Motor Claim Department

Claim Type: Third Party

Accident Date: 09/05/2022

TP Veh Reg No: SLG8366M

Estimate No: EST2200148

Date: 11 May 2022

Veh Reg No: SKA5715C

Make/Model: HONDA JAZZ 1.3L A

Chasis No: JHMGE68509S235457

Reg. Date: 15/03/2011

Your Ref No: SLG8366M

Xiao Tong

Estimate Repair Cost to Vehicle No :SKA5715C

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BOOT LID <i>Dented</i>	844.10 ✓	
2	2 PCS BOOT LID HINGE <i>new</i>	124.00 ✗	
3	1 PC BOOT LID "JAZZ" EMBLEM <i>new</i>	48.80 ✓	
4	1 PC BOOT LID LOGO <i>new</i>	50.20 ✗	
5	1 PC BOOT LID LOCK <i>Damaged</i>	189.50 ✓	
6	1 PC BOOT LID LOCK CHECKER <i>new</i>	38.90 ✗	
7	1 PC BOOT LID TRIM <i>cracked</i>	177.20 ✓	
8	1 PC BOOT LID RUBBER <i>cut</i>	182.40 ✓	
9	2 PCS REAR NUMBER PLATE LAMP <i>new</i>	124.80 ✗	
10	1 PC REAR WINDSCREEN RUBBER <i>new</i>	120.50 ✓	
11	1 PC REAR FENDER LH <i>Repair</i>	786.90 ✗	
12	1 PC REAR FENDER TRIM LH <i>Deformed</i>	286.50 ✓	
13	1 PC REAR FENDER TRIM RH <i>Deformed</i>	286.50 ✓	
14	1 PC REAR PANEL <i>Distorted</i>	496.50 ✓	
15	1 PC REAR PANEL TRIM <i>Deformed</i>	166.80 ✓	
16	1 PC SPARE TYRE PANEL <i>Buckled</i>	737.00 ✓	
17	1 PC SPARE TYRE PANEL SPONGE <i>cracked</i>	236.80 ✓	
18	1 PC REAR SPARE TYRE HARDBOARD <i>Deformed</i>	289.60 ✓	
19	1 PC TAIL LAMP LH <i>cracked</i>	366.40 ✓	288
20	1 PC TAIL LAMP - RH <i>cut</i>	366.40 ✓	288
21	1 PC REAR BUMPER <i>Deformed</i>	497.70 ✓	
22	2 PCS REAR BUMPER SIDE RETAINER <i>new</i>	93.60 ✓	
		6,511.10	
	Less 20%	1,302.22	5,208.88
	Special Net		
23	1 SET BOOTLID TRIM CLIPS <i>new</i>	60.00 30	
24	1 PC REAR NUMBER PLATE <i>new</i>	50.00 ✗	
25	1 PC REAR WINDSCREEN SEAL <i>new</i>	60.00 30	
26	1 PC REAR WINDSCREEN SEALANT <i>new</i>	60.00 30	
27	1 PC REVERSE CAMERA <i>new</i>	480.00 ✗	

5225.50

4183.60

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 09/05/2022
TP Veh Reg No: SLG8366M

Estimate No: EST2200148
Date: 11 May 2022
Veh Reg No: SKA5715C
Make/Model: HONDA JAZZ 1.3L A
Chasis No: JHMGE68509S235457
Reg. Date: 15/03/2011
Your Ref No: SLG8366M

Estimate Repair Cost to Vehicle No :SKA5715C

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
28	1 SET REAR FENDER TRIM CLIPS LH <i>3mm</i>	60.00 30	
29	1 SET REAR FENDER TRIM CLIPS RH <i>3mm</i>	60.00 30	
30	1 PC REAR FENDER LH SIDE GLASS SEAL <i>3mm</i>	60.00 x	
31	1 PC REAR FENDER LH SIDE GLASS SEALANT <i>750</i>	60.00 +	
32	1 SET REAR PANEL TRIM CLIPS <i>m</i>	30.00 20.	
33	1 PC REAR BUMPER LOWER SPOILER <i>2mm d</i>	600.00 50	
34	1 SET REAR BUMPER CLIPS <i>Nm</i>	40.00 30	
		1,620.00	1,620.00
	Labour		
35	1 TO CHECK WIRING	50.00 30	
36	1 TO REMOVE AND REFIT REAR BOOTLID SPOILER	80.00 x	
37	1 TO REMOVE AND REFIT THIRD BRAKE LIGHT	80.00 x	
38	1 TO REMOVE AND REFIT REAR VIEW CAMERA	80.00 50	
39	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00 50	
40	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00 ✓	
41	1 TO REMOVE AND REFIT REAR INNER TRIM	120.00 80	
42	1 TO REMOVE AND REFIT PETROL TANK	150.00 x.	
43	1 TO REMOVE AND REFIT LH FENDER SIDE GLASS <i>3050</i>	120.00 x.	
44	1 TO SPRAY UNDERSEAL	140.00 100	
45	1 TO REMOVE AND REFIT SEAT CUSHION	200.00 120.	
46	1 (REAR) TO SPRAY PAINTING	1,500.00 1200.	
47	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,600.00 1300.	
		4,320.00	4,320.00

AA

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 09/05/2022
TP Veh Reg No: SLG8366M

Estimate No: EST2200148
Date: 11 May 2022
Veh Reg No: SKA5715C
Make/Model: HONDA JAZZ 1.3L A
Chasis No: JHMGE68509S235457
Reg. Date: 15/03/2011
Your Ref No: SLG8366M

Estimate Repair Cost to Vehicle No :SKA5715C

Quantity	Description	List Price SS	Amount SS
		Total	S\$ 11,148.88
		Add GST @ 7%	780.42
		Total Amount Payable	<u>S\$ 11,929.30</u>

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND NINE HUNDRED TWENTY NINE AND CENTS THIRTY ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin Lj
L/S #1/05/22.

09 Days.

total: 768360

L/S: 64K

64K