

PEOPLE'S VEHICLE RECOVERY SERVICE

BLK 3023-A UBI ROAD 1 #01-60 SINGAPORE 408717

Tel No. : 67433246 / 67438552 Fax No. : 67430013

E-Mail : peoplevehicle@gmail.com

Tax Reg. No. : M90001895E Buss. Reg. No. : 31800200X

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY #07-16

CHARTIS BUILDING (S) 079120

Attention : Motor Claim Department

Contact : 6419 1826 Fax No. : 6415 3727

Asher.

Estimate : ES22008

Date : 10/05/2022

Vehicle Num. : SKP 7000 P

Make/Model : TOYOTA ESTIMA

Chassis/Eng# :

Accident Date : 07/05/2022

Claim No. : TP 416-22

Reference : SMD 9303 S

Policy No. : NTUC 5077768814-05

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	WINDSCREEN MOULDING REAR <i>new</i>		118.20
2.	1	TAILGATE <i>Painted</i>		1,819.10 1380
3.	1	TAILGATE OUTER MOULDING <i>zincd</i>		230.10
4.	2	TAILGATE LAMP <i>LH zincd</i>	580.10	1,160.20 373
5.	1	TAILGATE REFLECTOR <i>new</i>		189.10
6.	1	TAILGATE LOGO <i>new</i>		65.80
7.	1	TAILGATE ESTIMA EMBLEM <i>new</i>		72.30
8.	1	TAILGATE X EMBLEM <i>new</i>		48.20
9.	1	TAILGATE WEATHERSTRIP <i>new</i>		228.30
10.	1	TAILGATE INNER LOCK <i>new</i>		580.10 371
11.	1	TAILGATE INNER BOARD <i>framed</i>		580.10
12.	1	BUMPER REAR <i>Painted</i>		480.10
13.	2	BUMPER BRACKET REAR <i>new</i>	85.60	171.20
14.	2	BUMPER SIDE RETAINER REAR <i>new</i>	78.10	156.20
15.	1	END PANEL REAR <i>Painted</i>		780.10
16.	1	END PANEL TOP GARNISH REAR <i>Painted</i>		370.10
List Total S\$:				7,049.20
25.00% Discount S\$:				1,762.30
				5,286.90
SPECIAL NETT ITEMS :				
1.	1	REVERSE SENSOR <i>new</i>		200.00
2.	1	REVERSE CAMERA <i>new</i>		450.00
3.	1	WINDSCREEN GUM <i>new</i>		60.00
4.	1	NUMBER PLATE AND BASE REAR <i>new</i>		50.00
Special Nett Total S\$:				840.00

5214.30

3910.72

610

CONTINUE / ...

PEOPLE'S VEHICLE RECOVERY SERVICE

BLK 3023-A UBI ROAD 1 #01-60 SINGAPORE 408717

Tel No. : 67433246 / 67438552 Fax No. : 67430013

E-Mail : peoplevehicle@gmail.com

Tax Reg. No. : M90001895E Buss. Reg. No. : 31800200X

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY #07-16

CHARTIS BUILDING (S) 079120

Attention : Motor Claim Department

Contact : 6419 1826 Fax No. : 6415 3727

Estimate : ES22008

Date : 10/05/2022

Vehicle Num. : SKP 7000 P

Make/Model : TOYOTA ESTIMA

Chassis/Eng# :

Accident Date : 07/05/2022

Claim No. : TP 416-22

Reference : SMD 9303 S

Policy No. : NTUC 5077768814-05

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :

REMOVE & REPLACE ACCIDENT DAMAGED PARTS

SPRAY PAINTING ACCIDENT AFFECTED PARTS

REMOVE AND REFIX WINDSCREEN REAR

REMOVE AND REFIT REAR UPHOLSTERY, CARPET AND ETC.

CHECK REAR WIRING AND LIGHTING OPERATION

UNDERCOAT

Labour Total S\$:

1,200.00
900.00
120.00
150.00
50.00
120.00

2,560.00

1670

Adrian L
2/5 10/05/22

06 Days

total: 6190.72

2/5: 4950.

SingDollars : Eight Thousand Six Hundred Eighty-Six & Cents Ninety Only

E. & O.E.

Total S\$: 8,686.90

for PEOPLE'S VEHICLE RECOVERY SERVICE

Computer Generated Invoice.No Signature Required.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date: