



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0374/2022/JT
DATE : 12-May-22
WIP : 23591

Hui Rong -
06 Days.
\$5711.20.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/5/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR EU KEE HOE, GREGORY
ADDRESS : 21A SIMEI ST 4
#06-42 DOUBLE BAY RESIDENCE
SINGAPORE 97351206
TELEPHONE : HP +65 97351206
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900258786-02
VEHICLE NO : EP 2232 R
MODEL CODE : AUDI Q2 1.0 TFSI S TRONIC
MODEL YEAR : 19/12/2019
ENGINE NO : CHZ C32931
CHASSIS NO : WAUZZZGA6KA082665
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-May-22
PLACE OF ACCIDENT : SIMEI ROAD OUTSIDE SIMEI GREEN CONDO



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE EP 2232 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$ 280.00	✓ ✓
2	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$ 1,400.00	2x
3	TO DISMANTLE AND RENEW REAR BUMPER. TO CUT OUT AND WELD REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,000.00	500 1500
4	TO RESPRAY REAR BUMPER AND REAR END PANELLING.	\$ 2,000.00	550 1100
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 7,872.00	

Handwritten signatures and initials:
S.L.S.
S.L.S.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. EP 2232 R

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
1	REAR BUMPER <i>Delnd</i>	1	\$	1,363.00 <i>1090.40</i>		
2	REAR BUMPER FIXING PARTS <i>new</i>	1	\$	81.00 <i>+</i>		
3	REAR BUMPER SPOILER <i>Delnd</i>	1	\$	316.00 <i>252.80</i>		
4	REAR BUMPER TOWING EYE <i>new</i>	1	\$	48.00 <i>+</i>		
5	REAR LIGH REFLECTOR - LH / RH <i>new</i>	2	\$	68.00 <i>+</i>		
6	REAR BUMPER REINFORCEMENT BEAM <i>new</i>	1	\$	615.00 <i>+</i>		
7	REAR BUMPER HOLDING STRAP - LH / RH <i>new</i>	2	\$	30.00 <i>+</i>		
8	REAR BUMPER GUIDE SECTION- LH / RH <i>new</i>	2	\$	120.00 <i>+</i>		
9	REAR PARKING AID SENSOR - INNER <i>new</i>	2		TBC <i>+</i>		
10	REAR PARKING AID SENSOR SEAL RING <i>new</i>	4	\$	10.00 <i>+</i>		
11	REAR BUMPER WIRING SET <i>new</i>	1	\$	572.00 <i>+</i>		
12	AERIAL FOR KESSY - LOWER <i>new</i>	1	\$	79.00 <i>+</i>		
13	REAR END PANEL <i>3 Panel Dented</i>	1	\$	258.00 <i>206.40</i>		
14	REAR END PANEL REINFORCEMENT <i>Repair</i>	1	\$	773.00 <i>+</i>		
15	REAR END PANEL CONNECTING PLATE - LH / RH <i>new</i>	2	\$	92.00 <i>+</i>		
16	REAR WHEEL ARCH COVER - LH / RH <i>new</i>	2	\$	360.00 <i>287.20</i>		
17	REAR END PANEL TRIM <i>new</i>	1	\$	171.00 <i>+</i>		
18	ARYLIC SEALANT <i>new</i>	S/N	\$	180.00 <i>180</i>		
19	CAVITY WAX <i>new</i>	S/N	\$	140.00 <i>140</i>		
20	STONE CHIP <i>new</i>	S/N	\$	180.00 <i>180</i>		
21	METAL FILLER POWDER <i>new</i>	S/N	\$	280.00 <i>280</i>		
22	SUNDRIES <i>new</i>		\$	400.00 <i>22.40</i>		
TOTAL SPARE PARTS			:	\$ 6,136.00		
TOTAL LABOUR CHARGES			:	\$ 7,872.00		
GRAND TOTAL			:	\$ 14,008.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Adrian L
: 12/05/22

: Not Authorised, ~~03 Days~~ 06 Days
: S/S.

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT