

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

MSIAO Tony

Not Authorized
17/5/22
1/5 \$4200
4 days

VEHICLE No: SLU 8656C

1PC	REAR WINDSCREEN	11		\$1,488.10	X
1PC	REAR WINDSCREEN MOULDING	11	148.50	\$188.30	/
1PC	TAILGATE	11 / Bent	1365.10	\$1,685.10	/
1PC	TAILGATE OUTER GARNISH	11		\$344.80	X
1PC	TAILGATE REAR LOGO	11		\$168.50	X
1PC	TAILGATE 'C-HR' EMBLEM	11		\$96.80	X
1PC	TAILGATE 'HYBRID' EMBLEM	11		\$105.00	X
2PCS	TAILGATE REFLECTORS @\$650.00	11		\$1,300.00	X
1PC	TAILGATE REAR WIPER ARM	11		\$188.90	X
1PC	TAILGATE REAR WIPER MOTOR	11		\$620.00	X
1PC	TAILGATE WEATHERSTRIP	11		\$488.90	X
1PC	TAILGATE INNER LOCK	Bent	509.20	\$641.90	/
1PC	TAILGATE LOCK STIRKER	11		\$60.00	X
1PC	TAILGATE INNER TRIM	11		\$811.60	X
2PCS	TAILGATE INNER LOCK SENSOR @\$899.00	11		\$1,798.00	X
1PC	TAILGATE INNER HOLDER GARNISH	11		\$58.00	X
1PC	REAR BUMPER	11 / 2e	545.10	\$1,215.10	/
1PC	REAR BUMPER CENTRE BLACK GARNISH	green	425.10	\$488.90	/
1PC	REAR BUMPER: Beam	Bent	399.50	\$570.20	/
2PCS	REAR BUMPER REFLECTORS @\$85.00	11		\$170.00	X
2PCS	REAR BUMPER SIDE RETAINERS @\$65.00	11		\$130.00	X
1PC	REAR BUMPER SPONGE	11		\$199.80	X
2PCS	REAR BUMPER PDC SENSORS @\$285.00	11		\$570.00	200 s/n
1PC	REAR END PANEL OUTER	11		\$899.10	X
1PC	REAR END PANEL LOCK SENSOR	11		\$350.00	X
1PC	REAR END PANEL TOP GARNISH	11		\$468.90	X
2PCS	TAILLAMPS @\$1050.50	MS CNA	521.80	\$2,101.00	1PC
2PCS	TAILLAMP HOUSING PANELS @\$650.30	11		\$1,300.60	X
1PC	REAR FENDER	11		\$1,205.10	X
2PCS	REAR FENDER INNER TRIM BOARDS @\$685.10	11		\$1,370.20	X
1PC	REAR FENDER OUTER PROTECTOR O/S	11		\$399.20	/
1PC	REAR FLOOR PANEL	11		\$1,415.10	X
1PC	REAR FLOOR PANEL TOP BOARD	11		\$622.30	X
2PCS	REAR FLOOR PANEL SIDE TOOL SPONGES @\$450.00	11		\$900.00	X
1PC	REAR FLOOR PANEL CENTRE TOOLS SPONGE	11		\$520.80	X
1PC	REAR EXHAUST	11		\$885.10	X
1PC	REAR EXHAUST HEAT SHIELD	11		\$188.30	X
				\$26,013.60	

S.NETT

1SET	REAR BUMPER CLIPS	neu	\$50.00	✓
1PC	REAR WINDSCREEN SEALANT	neu	\$50.00	40
1PC	REAR WINDSCREEN INNER SEAL	neu	\$50.00	40
1PC	REAR END PANEL SEALANT	11	\$50.00	X
1SET	TAILGATE INNER TRIM CLIPS	11	\$50.00	X
1SET	REAR FLOOR PANEL INSULATOR	11	\$450.00	X
1SET	REAR FENDER INNER TRIM BOARD CLIPS	11	\$50.00	X
1SET	REAR REVERSE CAMERA	11	\$380.00	X
	TO CHECK WIRING		\$50.00	20
	TO DISMANTLE & REPLACED REAR PDC SENSOR		\$80.00	50
	TO DISMANTLE & REFIX REAR WINDSCREEN		\$150.00	120
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY		\$120.00	80
	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM		\$100.00	50
	TO DISMANTLE & REFIX REAR EXHAUST	11	\$100.00	X
	TO TRANSFER TAILGATE MECHANISM		\$100.00	60
	TO SPRAY PROOFING		\$180.00	30
	TO MOUNT VEHICLE ON CAR O-LINER	11	\$380.00	X
	LABOUR FOR PANEL BEATING & REPLACED PARTS		\$2,000.00	580
	TO PUTTY & SPRAY PAINTING		\$2,000.00	700
TOTAL			\$32,403.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-4313.50
 25-8:
 P-3235.12
 S.N-330
 L-1690
 5255.12
 203
 4204