



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
Tel: +65 67412845 Fax No: +65 67412170
Email: zero_gravity@singnet.com.sg
Reg.No.: 52888887X

QUOTATION

No : QT-000292

AIG ASIA PACIFIC INSURANCE PTE. LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attention: Motor Claim Department

TEL : 64193000

FAX :

Your Ref. : SLA7700U
Vehicle No. : SLX6307H
Make & Model : HYUNDAI ELANTRA
Chasis No. : KMHD841CMJU663148
Engine No. : G4FGJU164508
Accident Date : 09-05-2022
Policy No. : 5099144952-04
Date : 03-06-2022
Page : 1 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
1	REAR BUMPER <i>Deformed</i>	1.0 PCS	505.40	✓ 505.40
2	REAR BUMPER REINFORCEMENT <i>Dented</i>	1.0 PCS	315.70	✓ 315.70
3	REAR BUMPER LIP <i>Deformed</i>	1.0 PCS	255.70	✓ 255.70
4	REAR BUMPER REFLECTOR (L/H) <i>crushed</i>	1.0 PCS	50.40	✓ 50.40
5	REAR BUMPER REFLECTOR (R/H) <i>crushed</i>	1.0 PCS	50.40	✓ 50.40
6	BUMPER CLIP <i>new</i>	10.0 PCS	6.00	30 60.00
7	BUMPER BRACKET (R/H) <i>Deformed</i>	1.0 PCS	42.60	✓ 42.60
8	BUMPER BRACKET (L/H) <i>Deformed</i>	1.0 PCS	42.60	✓ 42.60
9	BUMPER SIDE RETAINER (L/H/R) <i>new</i>	1.0 PCS	32.10	✓ 32.10
10	BUMPER SIDE RETAINER (R/H/R) <i>new</i>	1.0 PCS	32.10	✓ 32.10
11	LAMP (REAR R/H/BOOT) <i>He new</i>	1.0 PCS	286.20	X 286.20
12	REAR BOOT <i>Dented</i>	1.0 PCS	1,883.80	1782 1,883.80
13	LOGO <i>new</i>	1.0 PCS	47.10	✓ 47.10
14	EMBLEM "ELANTRA" <i>new</i>	1.0 PCS	51.20	✓ 51.20
15	REAR BOOT WEATHERSTRIP <i>crushed</i>	1.0 PCS	126.80	✓ 126.80
16	REAR BOOT INNER LOCK <i>Damaged</i>	1.0 PCS	164.30	✓ 164.30
17	REAR END PANEL <i>Dented</i>	1.0 PCS	399.90	✓ 399.90
18	REAR END PANEL GARNISH <i>Deformed</i>	1.0 PCS	62.90	✓ 62.90
19	Discount 20 %			-881.84
20	SubTotal (L)			3,527.36
21	REAR END PANEL SEALANT <i>new</i>	1.0 BTL	50.00	✓ 50.00
22	REVERSE SENSOR <i>Damaged</i>	1.0 SET	280.00	250 280.00
23	REAR NUMBER PLATE <i>He new</i>	1.0 PCS	35.00	X 35.00
24	SubTotal (S)			365.00
25	TO PROVIDE UNDER TURFCOAT	1.0 X		60 120.00
26	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS	1.0 X		30 50.00
27	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	1.0 X		X 60.00



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
Tel: +65 67412845 Fax No: +65 67412170
Email: zero_gravity@singnet.com.sg
Reg.No.: 52888887X

QUOTATION

No : QT-000292

AIG ASIA PACIFIC INSURANCE PTE. LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attention: Motor Claim Department

TEL : 64193000

FAX :

Your Ref. : SLA7700U
Vehicle No. : SLX6307H
Make & Model : HYUNDAI ELANTRA
Chasis No. : KMHD841CMJU663148
Engine No. : G4FGJU164508
Accident Date : 09-05-2022
Policy No. : 5099144952-04
Date : 03-06-2022
Page : 2 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
28	TO REMOVE REVERSE SENSOR	1.0 X		80.00
29	TO TRANSFER REAR BOOT FITTING	1.0 X		120.00
30	PANEL BEATING & REPLACING OF THE ABOVE	1.0 X	1500	800.00
31	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0 X		750.00
32	Sub Total (LABOUR)			1,980.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 4942.36
L/s: 3.9K.
06 Days

SINGAPORE DOLLAR FIVE THOUSAND EIGHT HUNDRED SEVENTY TWO AND CENTS THIRTY
SIX ONLY

E. & O.E

Total	S\$	5,872.36
Discount	S\$	0.00
Net Total	S\$	5,872.36

Terms: C.O.D.

Customer's Signature/Co. Stamp

ZERO GRAVITY

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.