



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
BLUWEL AUTOMOTIVE SERVICE PTE LTD		Ref:	CS/TP22004555/Uvce2
BLK 1 KAKI BUKIT AVE 6		Date:	06/06/2022
#01-28/53/55/56 (MAIN OFFICE)SINGAPORE			
417883			
ON BEHALF OF LEE CHUAN KIT (LI CHUANJIE)		Code:	TP149
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.		Veh. Inspected	SGT 770Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	17/05/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	SKODA KAROQ (A)	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	TMBKR7NU1L5011020	Colour	GREY
Odometer	25934 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	BRIDGESTONE	8 mm
L/H Front Tyre	215/55 R17	BRIDGESTONE	8 mm
R/H Rear Tyre	215/55 R17	BRIDGESTONE	8 mm
L/H Rear Tyre	215/55 R17	BRIDGESTONE	8 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.			
DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	21/04/2022	Inspection Date	17/05/2022
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	