

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

AGH 30 018 4421

Name : TIMOTHY KOH HONG BOON
Vehicle No : SME 3759 U

TP Somp
vecon

Make/Model : TOYOTA ALPHARD
Accident date : 12.05.2022

No	DESCRIPTION	Qty	Amount (\$\$)
List Items			
1	Rear bumper <i>torn</i>	1	\$ 1,462.50 1244
2	Rear bumper side holder @ \$205.70 <i>RH Dmgd.</i>	2	\$ 411.40 95
3	Rear bumper RH reflector <i>not new</i>	1	\$ 205.30 x
4	Rear RH lamp lower garnish <i>Distorted</i>	1	\$ 445.50 ✓
5	Rear RH lamp <i>lit</i>	1	\$ 1,165.50 761
6	Rear RH lamp lower garnish side holder <i>Dmgd.</i>	1	\$ 206.70 x 66
7	Rear RH lamp panel <i>Repair</i>	1	\$ 445.40 x 3129.50
8	Rear RH fender top rubber <i>lit</i>	1	\$ 686.10 x 285
9	Rear tailgate RH side reflector <i>lit</i>	1	\$ 148.00 ✓ 2347.12
10	Rear tailgate "Alphard" emblem <i>New</i>	1	\$ 145.30 285
			\$ 5,321.70
Less 25% Disc			\$ 1,330.43
Total			\$ 3,991.28

Special Nett Items

1	Rear bumper clips (1 set) <i>new</i>	1	\$ 60.00 30
2	Rear reverse sensor (1 set) <i>not new</i>	1	\$ 380.00 x
Total			\$ 440.00

Labour Cost

1	To supply rear quarter glass sealant	\$ 50.00 ✓
2	Remove & reinstall quarter glass	\$ 100.00 60
3	Remove & reinstall reverse sensor	\$ 150.00 50
4	Remove & reinstall RH rear fender quarter glass	\$ 150.00 x 1260
5	Remove, replace & repair consistent to the accident	\$ 1,000.00 500
6	Respray painting	\$ 1,200.00 700
Total		\$ 2,650.00

Grand Total \$ 7,081.28

total: 3737.12
H/S: 3K
03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

3K