



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2206122

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 03/10/2022
Reference CC6/CTI22004560/Apa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SJH 1796U
Insured Veh. SJH 6967K
Claim No. SNM22D203291/C04
Policy No. DMPCSNW00035112200
Accident Date 12/05/2022
Inspection Date 12/05/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22004560/Apa3q2 Date: 03/10/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJH 6967K	Veh. Inspected	SJH 1796U	
Policy No.	DMPCSNW00035112200	Coverage (\$)	0.00	
Claim No.	SNM22D203291/C04	Excess (\$)	0.00	
Assign From		Assign Date	12/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JHMF25406S200062	Colour	GREEN	
Odometer	262278 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/05/2022	Inspection Date	12/05/2022	
Survey held at	ADVANCE AUTO GARAGE 23 KAKI BUKIT AVENUE 4, #04-01 VICOM KAKI BUKIT INSPECTION CENTER, SINGAPORE 415933.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 1796U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	638.40	638.40
2	REAR BUMPER SIDE HOLDER @\$24.60	NECESSARY	49.20	49.20
1	REAR END PANEL	DENTED	395.40	395.40
1	REAR END PANEL TOP GARNISH	DEFORMED	145.60	145.60
2	TAILLAMP @\$285.40	CRACKED	570.80	570.80
2	TAILLAMP PANEL @\$125.10	TO REPAIR SEE LABOUR	250.20	-
1	BOOTLID	DENTED	698.60	698.60
1	BOOTLID LOCK	DAMAGED	158.60	158.60
1	BOOTLID WEATHERSTRIPE	CUT	169.40	169.40
2	BOOTLID REFLECTOR @\$202.40	N/S CUT / O/S CRACKED	404.80	404.80
1	HONDA LOGO	NECESSARY	45.60	45.60
2	REAR FENDER INNER TRIM @\$245.10	NOT NECESSARY	490.20	-
1	SPARE TYRE PANEL TOP COVER	DEFORMED	275.40	275.40
1	REAR EXHAUST PIPE MOUNTING	NOT NECESSARY	39.40	-
1	REAR EXHAUST PIPE GASKET	NOT NECESSARY	35.10	-
2	FRONT BUMPER SIDE HOLDER @\$26.10	NECESSARY	56.20	56.20
1	FRONT BUMPER REINFORCEMENT	DENTED	268.40	268.40
2	HEADLAMP @\$989.60	CRACKED	1,979.20	1,979.20
2	HEADLAMP LOWER BRACKET @\$45.20	NOT NECESSARY	90.40	-
1	AIR CON CONDENSER	NOT NECESSARY	1,255.60	-
1	RADIATOR	NOT NECESSARY	1,410.20	-
	LESS 20% DISCOUNT		-	-1,171.12
			9,426.70	4,684.48
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR BUMPER LOWER SPOILER (SN)	DAMAGED	1,200.00	1,000.00
1	REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	20.00	20.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	60.00	60.00

Report Ref No. CC6/CTI22004560/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	TAILLAMP SPONGE GASKET @\$20.00 (SN)	NECESSARY	40.00	40.00
2	BOOTLID REFLECTOR SPONGE GASKER @\$20.00 (SN)	NECESSARY	40.00	40.00
1	REAR CAMERA (SN)	NOT NECESSARY	480.00	-
1	REAR FENDER INNER TRIM CLIPS (SN)	NOT NECESSARY	60.00	-
1	REAR EXHAUST PIPE (SN)	NOT NECESSARY	1,000.00	-
1	FRONT NUMBER PLATE (SN)	DEFORMED	30.00	30.00
1	FRONT NUMBER PLATE HOLDER (SN)	CRACKED	30.00	30.00
1	FRONT BUMPER (SN)	DEFORMED	1,300.00	1,000.00
1	FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT BUMPER LOWER SPOILER (SN)	NOT NECESSARY	600.00	-
1	FRONT BUMPER LOWER GRILLE (SN)	NOT NECESSARY	200.00	-
2	FRONT BUMPER FOG LAMP @\$350.00 (SN)	NOT NECESSARY	700.00	-
2	FRONT BUMPER FOG LAMP COVER @\$150.00 (SN)	NOT NECESSARY	300.00	-
1	FRONT GRILLE (SN)	CRACKED	480.00	350.00
1	FRONT GRILLE LOGO (SN)	NECESSARY	80.00	80.00
1	FRONT GRILLE CLIPS (SN)	NECESSARY	20.00	20.00
			6,980.00	2,930.00
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL.		1,800.00	1,500.00
	SPRAY PAINTING.		1,800.00	1,500.00
	WIRING.		100.00	60.00
	TO REMOVE REVERSE SENSOR .		100.00	50.00
	TO REMOVE REAR CAMERA.		100.00	50.00
	TO SPRAY TUFF COAT.		180.00	80.00
	TO REMOVE UPHOLSTERY .		150.00	80.00
	TO TRANSFER BOOTLID FITTINGS.		150.00	60.00
	TO REMOVE EXHAUST PIPE .	NOT NECESSARY	150.00	-
	TO REMOVE CONDENSER AND TO TOP UP AIR CON GAS.	NOT NECESSARY	120.00	-
	TO REMOVE RADIATOR AND TO TOP UP COOLANT.	NOT NECESSARY	120.00	-
			4,770.00	3,380.00
GRAND TOTAL			21,176.70	10,994.48

Report Ref No. CC6/CTI22004560/Apa3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,800.00
---	--	--	----------

Report Ref No. CC6/CTI22004560/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJH 1796U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJH 1796U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJH 1796U

RE-INSPECTION

