

TP Chinn
Xiao Tony.

SJH17964 2008 July.
Honda Civic 1998 cc
JH MFD25406 S200062

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplemental item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rear Bumper	Dented	638.40 ✓
Rear Bumper Clips.	✓	30(SN) ✓
Rear Bumper Side Holder x 02	✓	24.6 x 2 = 49.20 ✓
Rear Bumper lower Spoiler	Dmgd	1200(SN) 1000(SN)
Reverse Sensor	Dmgd	280(SN) 200(SN)
Rear End Panel	Dented	395.40 ✓
Rear End Panel Top Garnish	Dented	145.60 ✓
Rear End Panel Top Garnish Clips.	✓	20(SN) ✓
Rear End Panel Sealant.	✓	60(SN) ✓
Taillap x 02	Crushed	285.4 x 2 = 570.80 ✓
Taillap Sponge Gasket x 02	✓	20 x 2 = 40(SN) ✓
Taillap Panel x 02	Rejis	125.1 x 2 = 250.20 ✓
Bootlid	Dented	698.60 ✓
Bootlid Lock	Damaged	158.60 ✓
Bootlid Weatherstripe.	✓	169.40 ✓

SJH 1796 U.

Bootlid Reflector x 02

LH at, RH angled

$202.4 \times 2 = 404.80$

Bootlid Reflector Sponge Basket x 02

per

$20 \times 2 = 40 (SN)$

Honda Logo.

per

45.60 ✓

Rear Camera.

HP ✓

480 (SN). ✕

Rear Fender Inner Trim x 02

$245.1 \times 2 = 490.20$

Rear Fender Inner Trim Clips.

} HP
per

60 (SN) ✕

Spere Tyre Panel Top Cover. Dehnd

275.40 ✓

Rear Exhaust Pipe.

1000 (SN) ✕

Rear Exhaust Pipe Mounting.

} HP

39.40 ✕

Rear Exhaust Pipe Gasket.

} per

35.10 ✕

SJH1796U.

Front Number Plate	Del'd	30(SN)	✓
Front Number Plate Holder	Cut'd	30(SN)	✓
Front Bumper	Del'd	1300(SN) 1000(SN)	
Front Bumper Clips.	new	30(SN)	✓
Front Bumper Side Holder x 02	new	$26.1 \times 2 = 56.20$	✓
Front Bumper Reinforcement.	Dented	268.40	✓
Front Bumper lower Spoiler	new	600(SN)	✗
Front Bumper lower Grille.	} NP new	200(SN)	✗
Front Bumper Fog Lamp x 02		$350 \times 2 = 700(SN)$	✗
Front Bumper Fog Lamp Cover x 02		$150 \times 2 = 300(SN)$	✗
		350(SN)	
Front Grille	Cut'd	480(SN)	✓
Front Grille Logo	} new	80(SN)	✓
Front Grille Clips.		20(SN)	✓
Headlamp x 02	Cut'd	$985.6 \times 2 = 1979.20$	✓
Headlamp lower Bracket x 02	NP new	45.2 $45.2 \times 2 = 90.40$	✗

STH 1796u.

Air Con Condenser } NH
Radiator. } over

5855.60
4684.48

S.N. 2930

1255.60 X

1410.20. X.

Panel Beating

Spry Painting.

Wiring.

To remove cruise sensor

To remove rear camera.

To spray tuff coat

To remove upholstery.

To transfer bootlid fittings.

To remove exhaust pipe.

To remove condenser and to }
top up air con gas }

To remove radiator and to }
top up coolant }

~~1800~~ 1500

~~2800~~ 1500

~~100~~ 60

~~100~~ 50

~~100~~ 50

~~180~~ 80

~~150~~ 80

~~150~~ 60

150 +

120 + 3380

120. +

total: 10994.48

L/S: 8.8K.

10 Days.

8,800
10 days