

GREEN FOREST AUTOMOBILE PTE LTD

8 KAKI BUKIT AVE 4 #05-25 PREMIER @ KB SINGAPORE 415875

CARRO LEASING PTE LTD
25 KAKI BUKIT ROAD4
05-26 SYNERGY @KB
Singapore 417800

T? AIG.
Xiao Tong
20th MAY 2022

MR053REH104551446

Accident date: 12nd MAY 2022

Estimated repair cost for vehicle no: SND5197X TOYOTA COROLLA ALTIS 1.6

S/n	Qty	Items	U/price	Amount
1	1	headlamp top chrome -RH <i>new</i>		\$188.00 <i>x</i>
2	1	Front headlamp -RH <i>new</i>		\$1,380.00 <i>✓</i>
3	1	Front grille <i>2</i>		\$315.00 <i>x</i>
4	1	grille clips <i>1M</i>		\$50.00 <i>x</i>
5	1	Front grille emble logo <i>new</i>		\$65.00 <i>x</i>
6	1	Front bumper <i>Behind.</i>		\$820.00 <i>581</i>
7	2	Front Bumper Side Bracket <i>new</i>	\$123.20	\$246.40 <i>x</i>
8	8	Front bumper clips <i>new</i>	\$12.90	\$103.20 <i>30</i>
9	1	Front bumper number plate <i>3M</i>		\$50.00 <i>x</i>
10	2	front bumper side bracket <i>new</i>	\$135.00	\$270.00 <i>x</i>
11	2	front bumper side retainer <i>new RH</i>	\$165.20	\$330.40 <i>65</i>
12	1	Front bumper fog lamp cover-RH <i>new</i>		\$155.00 <i>x</i>
13	1	Front fog lamp -RH <i>new</i>		\$254.00 <i>✓</i>
14	1	water tank <i>Behind</i>		\$285.00 <i>110.</i>
15	1	Front fender -RH <i>new</i>		\$855.00 <i>x</i>
16	1	Front fender mud shield -RH <i>new</i>		\$153.90 <i>x</i>
17	1	Front fender inner cowling -RH <i>new</i>		\$184.00 <i>✓</i>
18	8	Front fender cowling clips <i>new</i>	\$12.90	\$103.20 <i>30.</i>
19	1	Front tyre-RH <i>new</i>		\$350.00 <i>x</i>
20	1	Front sport rim-RH <i>new</i>		\$500.00 <i>✓</i>
21	1	Front shock absorber - RH <i>new</i>		\$385.00 <i>x</i>
22	1	Front knuckle arm- RH <i>new</i>		\$285.00 <i>✓</i>
23	1	Front lower arm- RH <i>new</i>		\$295.00 <i>✓</i>
24	1	Front wheel bearing- RH <i>new</i>		\$188.00 <i>✓</i>

Labour charges

To remove & refit cushion

To remove & refit front undercarriage

To check wheel alignment computer

To check wiring

Tuff kote

Panel beating

Spray painting

LKK Auto Consultants hence notify

The Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Subtotal :- \$7,811.10

\$120.00 *x*

\$280.00 *200*

\$150.00 *80*

\$80.00 *30*

\$120.00 *30*

\$800.00 *300*

\$800.00 *200*

Subtotal :- \$2,350.00

Total:- \$10,161.10

3902
2926.50

840

total: 3766.50

H/S: 3K

058 days