



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

Policy No: DHOM120061152100
DOA: 07/05/2022@1700

Steve (LKH)

14/6/22, 377

UNITED OVERSEA INSURANCE LTD

14.6.2022

ATTN: THE MOTOR CLAIMS DEPT

OD CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:
GBL 3717 J - NISSAN CABSTAR SINGLE CAB MT
CHASSIS NO: JN1SA2F24Z0000329 (06/2021)

SUPPLEMENTARY

1 Steering cover set	✓ BR	\$ 160.00
1 Front SD panel RH	✓ OO	\$ 290.00
1 Tilt hinge bracket RH	✓ BR	\$ 150.00
1 Tilt hinges bracket cushion	✓ APC	\$ 60.00
1 Front RH headlamp lower apron	✓ BR	\$ 70.00
1 Front SD garnish RH	(mirror garnish) ✓ BR	\$ 95.00
1 Tilt hinge bracket LH	✓ ?	\$ 150.00
1 Tilt hinge bracket cushion	✓ ?	\$ 60.00

\$ 1,035.00

Cost plus 10%

\$ 103.50

\$ 1,138.50

Labour to remove and refix dashboard to
enable repair

\$ 250.00 200

Repair front dashboard

\$ 250.00 200

Labour to jacking front LH/RH chasis and
RH/LH rod

\$ 950.00 400 400

Repair wiper linkage bracket (and all other parts)

\$ 250.00 100

~~X Remove and repair Hydraulic pipe with oil~~

~~\$ 130.00~~

Labour to remove/replace aircon blower and

2800
To repair air con pipe and repair to refricabe)

\$ 250.00

\$ 3,598.50

150