

創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

Policy No: DHOM120061152100

DOA: 07/05/2022@1700

UNITED OVERSEA INSURANCE LTD


13/5/2022

ATTN: THE MOTOR CLAIMS DEPT

OD CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:
GBL 3717 J - NISSAN CABSTAR SINGLE CAB MT
CHASSIS NO: JN1SA2F24Z0000329 (06/2021)

1 pc	Front windscreen	\$ 700.00
2 pcs	Front windscreen moulding LHS @ \$70	\$ 140.00
2 pcs	Front windscreen moulding RHS @ \$70	\$ 140.00
1 pc	Front panel	\$ 800.00
1 pc	Front wiper garnish	\$ 380.00
1 pc	Front wiper blade LHS	TBC
1 pc	Front wiper blade RHS	TBC
1 pc	Front wiper arm LHS	\$ 120.00
1 pc	Front wiper arm RHS	\$ 120.00
1 pc	RHS side mirror	\$ 150.00
1 pc	Front headlamp LHS	\$ 320.00
1 pc	Front headlamp RHS	\$ 320.00
1 pc	Front headlamp lower garnish LHS	\$ 80.00
1 pc	Front headlamp lower garnish RHS	\$ 80.00
1 pc	Front bumper	\$ 700.00
1 pc	Wiper linkage LHS	\$ 150.00
1 pc	Wiper linkage RHS	\$ 150.00
1 pc	Wiper motor	\$ 450.00
1 pc	Wiper nozzle LHS	TBC
1 pc	Wiper nozzle RHS	TBC
1 pc	Front panel 'CABSTAR' emblem	\$ 50.00
1 pc	Front grille	\$ 350.00
1 pc	Horn LHS	\$ 100.00
1 pc	Horn RHS	\$ 100.00
1 pc	Front center rod	TBC
1 pc	Steering	TBC
1 pc	Dashboard	TBC
1 pc	Dashboard meter	TBC
1 pc	Air-con blower (complete)	\$ 650.00



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

GBL 3717 J - NISSAN CABSTAR SINGLE CAB MT

1 pc	A/C liquid pipe	TBC
1 pc	A/C suction pipe	TBC
3 pcs	Brake pipe	TBC
3 pcs	Hydraulic x 3	TBC
1 pc	Chassis support panel	TBC
1 pc	RH side panel	TBC
1 pc	Heater assy	\$ 1,700.00
		<u>\$ 7,750.00</u>
	COST PLUS 10%	\$ 775.00
		<u>\$ 8,525.00</u>
1 pc	Front no.plate (S/NETT)	\$ 35.00
1 pc	Windscreen sealant (S/NETT)	\$ 35.00
	Remove and replace front windscreen	\$ 150.00
	Check wiring function	\$ 40.00
	Remove and replace steering shaft	\$ 280.00
	Remove and reinstall cabin to enable repair	\$ 500.00
	Labour charges for the above repair.	\$ 1,800.00
	Putty and respray all accident affected areas.	\$ 950.00
		<u>\$ 12,315.00</u>
	ADD 7% GST	\$ 862.05
		<u><u>\$ 13,177.05</u></u>

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

Page 2 of 2

CHARN'S CUSTOMCRAFT

.....
