

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Monday, 20 June 2022 11:25 AM  
**To:** charns@singnet.com.sg  
**Cc:** SUR  
**Subject:** RE: UOI-OD GBL 3717J DOA: 07/05/2022  
**Attachments:** GBL3717 SUPP 2.pdf; GBL 3717 supp.pdf

Dear Sir/Madam,

Kindly proceed the supplementary as attached with our surveyor marking.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>

**Sent:** Thursday, 19 May 2022 4:37 PM

**To:** charns@singnet.com.sg

**Cc:** SUR <sur@lkkauto.com>

**Subject:** UOI-OD GBL 3717J DOA: 07/05/2022

Dear Sir/Madam,

As instructed by our client, please proceed to repair the insured vehicle **GBL 3717J. (Excess \$500/-)**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their rights not to pay if there is no valid approval obtained before repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)