ASS. REC. BY: 51616 CS (1017) 604566 EQUIS				
ASSI	CHMENT			
From: Date:	Veh No: (BL 3717) Yr Regn: 29/6/71			
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry Taxl / Prime Mover /			
QD TP/WS/TP RES/ OD RES/ EVA / INV/ MV	Truck / Trailer or			
To Inspect Vehicle No:	Make Nicson Catatac 1000			
et Workshop m/s	Colour Z/LC AC: Insured / Std / NI / NA			
0[Sp.Reading 43087 T/Radio; Insured / Std / NI / NA			
Insured:	Eng/No:			
Policy No.	CNO: JN ISA 2 FOLK 7- 000 6 3 29			
Clalms No. M12D18382205	Gen. Cond: Good / Fair / Poor / Burnt			
Sum Insured: Excess: 500/-	Steering: Inorder / Jammed / Leaked / Burnt or			
(Client's Record)	Brake: Inorder/Jammed/Leaked/Burnit or			
Make of Veh;	Modi: NII / S/Rim / STD A/Rim or			
2/20/	Tyre Size: F: 195 \$ 150			
(Policy Condition)	R: /)			
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA (GY) FS / LIZA / MIC / OHTSU / PIR / SUMI /			
repair at the time of inspection.	TOYO/YOKO or			
Bal. or Market Value:	Fron! Rear			
DAC Accident Rport: Consistent? : Yes or No	R/Bal, mm R/Bal mm			
GIA / PR Seen: Consistent? : Yes or No	UBal. UBal. UBal.			
Est Repairs: days Res.: Yes or No	D.O.A. 715174			
Lum Sum: % · 3 Val.: Yes or No	Survey held at (harn)			
CA REV REP. 24 HRS	Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or			
Vehicle: IN/OUT Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.			
Date / Time Action / Instruction	The O/O / Chassis frame / Body Structure Shected due to comision.			
1 NV-68K				
18/05/22@1.58pm revert to Josephine Won				
19/05/22@4.31pm Josephine Wong informe				
19/05/22@4.37pm Informed wksp C/A & ex	\$500 by email.			
Osle/Time, File Pass to? : Prell. Report	Days Of Repair:			
(1) : Final Report				
Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee:			
2) Add Fe	Transportation:			
	Jatonian (6			
Report Formal:	: Interview (\$) Photos : Tech, Invs (\$) Others			
Lump Sum / LS.4: (%	: Weel end (%			
	(mark)			
	FOTAL			



Customerapt

Accident Claim Repair, Corroston Welding, Body Dent Repairs, Spray-Painting, Mechanical Repair And Customizing of Cars BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724 BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723 TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg Bus. Reg. No. 251513/00M

Policy No: DHOM120061152100

DOA: 07/05/2022@1700

UNITED OVERSEA INSURANCE LTD

13/5/2022

ATTN: THE MOTOR CLAIMS DEPT

OD CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO: GBL 3717 J - NISSAN CABSTAR SINGLE CAB MT CHASSIS NO: JN1SA2F24Z0000329 (06/2021)

1 pc	Front windscreen / BK	\$	700.00
2 pcs	Front windscreen moulding LHS @ \$70 / PC	\$	140.00
2 pcs	Front windscreen moulding RHS @ \$70 /	\$	140.00
1 pc	Front panel / ///	\$	800.00
1 pc	Front wiper garnish $\sim \eta \eta$	\$	380.00
1 pc	Front wiper blade LHS / (1)	TBO	C
1 pc	Front wiper blade RHS / (9	TBO	C
1 pc	Front wiper arm LHS / []	\$	120.00
1 pc	Front wiper arm RHS / //	\$	120.00
1 pc	RHS side mirror / B7	\$	150.00
1 pc	Front headlamp LHS	\$	320.00
1 pc	Front headlamp RHS / GR	\$	320.00
1 pc	Front headlamp lower garnish LHS	\$	80.00
1 pc	Front headlamp lower garnish RHS / fl	\$	80.00
1 pc	Front bumper / //	\$	700.00
1 pc	Wiper linkage LHS	\$	150.00
1 pc	Wiper linkage RHS	\$	150.00
1 pc	Wiper motor ?	\$	450.00
1 pc	Wiper nozzle LHS / Of	TBO	C
1 pc	Wiper nozzle RHS / / / / / / / / / / / / / / / / / / /	TBO	C
1 pc	Front panel 'CABSTAR' emblem / MC	\$	50.00
1 pc	Front grille / MIS	\$	350.00
1 pc	Horn LHS / P7	\$	100.00
l pc	Horn RHS	\$	100.00
1 pc	Front center rod / BI (cabin fill lod)	TB	C
1 pc	Steering ?	TB	C
l pc	Dashboard	TB	C
l pc	Dashboard meter	TB	C
1 pc	Air-con blower (complete)	\$	650.00
	Page 1 of 2		



Spray-Painting, Mechanical Repair And Customizing of Cars BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724 BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723 TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg Bus. Reg. No. 251513/00M

GBL 3717 J - NISSAN CABSTAR SINGLE CAB MT

	44	and.
1 pc	A/C liquid pipe	TBC
1 pc	A/C suction pipe	TBC
3 pcs	Brake pipe - RT	TBC
3 pcs	Hydraulic x 3	TBC
l pc	Chassis support panel	TBC
	RH side panel / 00)	TBC
l pc	Heater assy	\$ 1,700.00
l pc	Heater assy	\$ 7,750.00
	COST PLUS 10%	\$ 775.00
	COST PLOS 1076	\$ 8,525.00
		4 3,2 2 3 3 3
	Front no.plate (S/NETT) / Ø	\$ 35.00
l pc		\$ 35.00
1 pc	Windscreen sealant (S/NETT) / //	ŷ 55.00
	Description of the state of the	\$ 150.00 <i>[20</i>
	Remove and replace front windscreen	\$ 40.00 39
	Check wiring function	\$ 280.00 250
	Remove and replace steering shaft	\$ 500.00 /
	Remove and reinstall cabin to enable repair	\$ 300.00 /
		\$ 1,800.00 1499
	Labour charges for the above repair.	\$ 1,800.00 1779
		\$ 950.00 900
	Putty and respray all accident affected areas.	
		\$ 12,315.00
	ADD 7% GST	\$ 862.05
		\$ 13,177.05

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

Page 2 of 2

CUSTOMCRAFT

uto Consultants hence notify Repairer of the following: To resurvey before/after spray painting display damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

Ston (LKK) 17/5/22, 4.201 OP- M 11 EXCeir- ?



United Overseas Insurance Limited

3 Anson Road #28-01 Springleaf Tower Singapore 079909

Tel (65) 6222 7733 Fax (65) 6327 3869 / 6327 3870 Email: ContactUs@uoi.com.sg uoi.com.sg

Co. Reg. No. 197100152R

ORIGINAL

R

BIZDRIVE-COMM THE SCHEDULE

Policy Number DHOM120061152100 Class of Policy MOTOR A000408 Agency A000408 Issued on 16/07/2021 in UOI Account Replacing Cover Note 20135574 Acceptance Date 13/07/2021 0001029 Client Period of Insurance from 29/06/2021 to 28/06/2023, both dates inclusive LIP TAT ENGINEERING ENTERPRISE Insured's Name.... 25 TUAS AVENUE 13 Mailing Address... #01-13 SINGAPORE 638991 Business/Occupn... ELECTRICAL WORKS Financial interest UNITED OVERSEAS BANK LIMITED SGD1,356.53 Premium BASIC ANNUAL PREMIUM SGD294.90-20.00% NO CLAIM BONUS SGD50.00 SRCC & FLOOD SGD2,223.26 Premium Due SGD1,111.63 Total Annual Premium SGD155.63 Premium GST SGD2,378.89 Total Due BIZDRIVE-COMM NISSAN CABSTAR WITH HOOD [CANVAS] Risk No. 001 Make/Model .. 1. Registration GBL3717J Body Type LORRY 1 Type of Cover COMPREHENSIVE No. of seats Yr of Manuf/Regn 2021/2021 NCB%............ 20.00 Capacity cc's Engine No. .. QR20018228R (2021) Chassis No. JN1SA2F24Z0000329 Certificate Ref. STT 2.00 model) Tonnage MARKET VALUE INDEMNITY FOR TOTAL LOSS... SGD500.00 SECTION 1 SGD100.00 WINDSCREEN DAMAGE CLAIM SGD3,000.00

THE FOLLOWING CLAUSES AND ENDORSEMENTS APPLY TO THIS POLICY 2 YEAR PLAN

15 & 15(B) & 15 (C)

AIR-CON/RADIO-CASS/CD COVERAGE INCLUSIVE

2 - EXCESS - DAMAGE CLAIMS

APPL TO <25 YRS & OR <3YRS EXP

AN EXCESS OF \$100 (BEFORE GST) APPLIES FOR EACH WINDSCREEN CLAIM

25 - STRIKE RIOT AND CIVIL COMMOTION

2 E - YOUNG AND INEXPERIENCED DRIVERS

30 - REPLACEMENT PARTS

57 - INCLUSION OF SPECIAL PERILS

89 [UNLIMITED WINDSCREEN COVER)

72(B) - LEGAL LIABILITY OF PASSENGERS FOR ACTS OF NEGLIGENCE

POLICY OWNERS'PROTECTION SCHEME

SANCTION LIMITATION AND EXCLUSION CLAUSE

Authorised Drivers for vehicle(s) with Certificate Ref. STT MZ 801



