



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

Policy No: DHOM120061152100
DOA: 07/05/2022@1700

UNITED OVERSEA INSURANCE LTD

13/5/2022

ATTN: THE MOTOR CLAIMS DEPT

OD CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:
GBL 3717 J - NISSAN CABSTAR SINGLE CAB MT
CHASSIS NO: JN1SA2F24Z0000329 (06/2021)

1 pc	Front windscreen	BR			\$	700.00	✓
2 pcs	Front windscreen moulding LHS @ \$70	BR			\$	140.00	✓
2 pcs	Front windscreen moulding RHS @ \$70	BR	X	NN	\$	140.00	X
1 pc	Front panel	BR			\$	800.00	✓
1 pc	Front wiper garnish	BR			\$	380.00	✓
1 pc	Front wiper blade LHS	BR	X	NN	TBC		X
1 pc	Front wiper blade RHS	BR	X	NN	TBC		X
1 pc	Front wiper arm LHS	BR			\$	120.00	✓
1 pc	Front wiper arm RHS	BR	X	NN	\$	120.00	X
1 pc	RHS side mirror	BR	X	NN	\$	150.00	X
1 pc	Front headlamp LHS	BR	X	NN	\$	320.00	X
1 pc	Front headlamp RHS	BR			\$	320.00	✓
1 pc	Front headlamp lower garnish LHS	BR	X	NN	\$	80.00	X
1 pc	Front headlamp lower garnish RHS	BR	X	NN	\$	80.00	X
1 pc	Front bumper	BR			\$	700.00	✓
1 pc	Wiper linkage LHS	BR	X	NN	\$	150.00	X
1 pc	Wiper linkage RHS	BR	X	NN	\$	150.00	X
1 pc	Wiper motor	BR	X	NN	\$	450.00	X
1 pc	Wiper nozzle LHS	BR	X	NN	TBC		X
1 pc	Wiper nozzle RHS	BR	X	NN	TBC		X
1 pc	Front panel 'CABSTAR' emblem	BR	X	NN	\$	50.00	X
1 pc	Front grille	BR			\$	350.00	✓
1 pc	Horn LHS	BR			\$	100.00	✓
1 pc	Horn RHS	BR	X	NN	\$	100.00	X
1 pc	Front center rod	BR (cabin alt red)	X	R	TBC		X
1 pc	Steering	BR	X	NN	TBC		X
1 pc	Dashboard	BR	X	NN	TBC		X
1 pc	Dashboard meter	BR	X	NN	TBC		X
1 pc	Air-con blower (complete)	BR	X	NN	\$	650.00	X



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

GBL 3717 J - NISSAN CABSTAR SINGLE CAB MT

1 pc	A/C liquid pipe	✓	BB	TBC	60	✓
1 pc	A/C suction pipe	✓	BB	TBC	60	✓
3 pcs	Brake pipe	✓	× NN	TBC	×	
3 pcs	Hydraulic x 3	✓	× NN	TBC	×	
1 pc	Chassis support panel	✓	× NN	TBC	×	
1 pc	RH side panel	✓	× NN	TBC	×	
1 pc	Heater assy	✓	× NN	\$	1,700.00	×
				\$	7,750.00	3710
				\$	775.00	+10%
				\$	8,525.00	4103

COST PLUS 10%

1 pc	Front no.plate (S/NETT)	✓	BT	\$	35.00	✓
1 pc	Windscreen sealant (S/NETT)	✓	PC	\$	35.00	✓ 70

Remove and replace front windscreen
Check wiring function
Remove and replace steering shaft
Remove and reinstall cabin to enable repair

\$	150.00	120
\$	40.00	30
\$	280.00	250
\$	500.00	/

Labour charges for the above repair.

\$	1,800.00	1400
----	----------	------

Putty and respray all accident affected areas.

\$	950.00	900
\$	12,315.00	

ADD 7% GST

\$	862.05	
\$	13,177.05	3200

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

Page 2 of 2
CHARN'S CUSTOMCRAFT

..... I, the Client, hereby acknowledge and agree to the following terms and conditions of the repair work:


- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve (LKK) total - 7373
17/5/22, 4.30pm supp 1 - 2057.50
OP- M AL supp 2 - 1115
EX cell - ? supp 3 - 1049.40
P/P
M BCL by
12 days
11,594.90



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
 Spray-Painting, Mechanical Repair And Customizing of Cars
 BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
 BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
 TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
 Bus. Reg. No. 251613/00M

Policy No: DHOM120061152100
 DOA: 07/05/2022@1700

Steve (LKH)

14/6/22, 3pm

UNITED OVERSEA INSURANCE LTD

14.6.2022

ATTN: THE MOTOR CLAIMS DEPT

OD CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:
 GBL 3717 J - NISSAN CABSTAR SINGLE CAB MT
 CHASSIS NO: JN1SA2F24Z0000329 (06/2021)

SUPPLEMENTARY

1 Steering cover set / BR	\$ 160.00	✓ (LKH)
1 Front SD panel RH / 00	\$ 290.00	✓ (LKH)
1 Tilt hinge bracket RH / BR	\$ 150.00	✓ (LKH)
1 Tilt hinges bracket cushion / APC	\$ 60.00	✓ 5
1 Front RH headlamp lower apron / BR	\$ 70.00	✓ 5
1 Front SD garnish RH (Mirror garnish) / BR	\$ 95.00	✓ 5
1 Tilt hinge bracket LH ? X NN	\$ 150.00	
1 Tilt hinge bracket cushion ? X NN	\$ 60.00	
	\$ 1,035.00	
Cost plus 10%	\$ 103.50	
	\$ 1,138.50	
Labour to remove and refix dashboard to enable repair	\$ 250.00	700
Repair front dashboard	\$ 250.00	700
Labour to jacking front LH/RH chasis and RH/LH rod	\$ 950.00	400 400
Repair wiper-linkage bracket (and all other parts)	\$ 250.00	100
X Remove and repair Hydraulic pipe with oil	\$ 130.00	
Labour to remove/replace aircon blower and heater (gas) 2pc	\$ 250.00	100 100
To repair air con pipe and repair to refricabe)	\$ 250.00	150
	\$ 3,598.50	

\$825.00
 +10%
 Parts 907.50 ✓

Labour
 \$1050
 1330
 1150 ✓

grille 100
 grille clip
 wiper cap
 No3 pipe

Labour to repair Heater assy \$380

total - 2057.50



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

Policy No: DHOM120061152100
DOA: 07/05/2022@1700

UNITED OVERSEA INSURANCE LTD


14.6.2022

ATTN: THE MOTOR CLAIMS DEPT

OD CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
GBL 3717 J - NISSAN CABSTAR SINGLE CAB MT
CHASSIS NO: JN1SA2F24Z0000329 (06/2021)
SUPPLEMENTARY

Labour to repair HEATER assy.---photo taken	(no stock)	\$	380.00	200 -
Air con blower (complete)----photo taken	BR (cost)	\$	650.00	+10%
Labour to remove and replace aircon blower and heater		\$	280.00	80 -
To refill gas	650 +10% 715	\$	120.00	✓
	400	\$	1,430.00	1495
	total - 1115			

CHARN'S CUSTOMCRAFT



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

Policy No: DHOM120061152100
DOA: 07/05/2022@1700

UNITED OVERSEA INSURANCE LTD

22.6.2022

ATTN: THE MOTOR CLAIMS DEPT

OD CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

GBL 3717 J - NISSAN CABSTAR SINGLE CAB MT

CHASSIS NO: JN1SA2F24Z0000329 (06/2021)

SUPPLEMENTARY 2

Grille X NN	\$ 5.00 X
Grille clip / NK	\$ 5.00 ✓
Wiper arm cover / OR	\$ 8.00 ✓
Grille logo / NK	\$ 58.00 ✓
Nosel connector (nose wiper) - OR	\$ 24.00 ✓
Side mirror cover (RH) - NK	\$ 19.00 ✓
Radiator / BT	\$ 780.00 ✓
Front panel sticker / NK	\$ 60.00 ✓
	\$ 959.00
Cost plus 10%	\$ 95.90
	\$ 1,054.90

total - 954
+10%
1049.40

Steve (LKK)
29/6/22

CHARN'S CUSTOMCRAFT