

# CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,  
Spray-Painting, Mechanical Repair And Customizing of Cars  
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724  
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723  
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg  
Bus. Reg. No. 251613/00M

Policy No: DHOM120061152100  
DOA: 07/05/2022@1700

Steve (LKH)

14/6/22, 3pm

UNITED OVERSEA INSURANCE LTD

14.6.2022

ATTN: THE MOTOR CLAIMS DEPT

## OD CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:  
GBL 3717 J - NISSAN CABSTAR SINGLE CAB MT  
CHASSIS NO: JN1SA2F24Z0000329 (06/2021)

## SUPPLEMENTARY

|                                                             |                      |         |
|-------------------------------------------------------------|----------------------|---------|
| 1 Steering cover set / BR                                   | \$ 160.00            | ✓ (LKH) |
| 1 Front SD panel RH / 00                                    | \$ 290.00            | ✓ (LKH) |
| 1 Tilt hinge bracket RH / BR                                | \$ 150.00            | ✓ (LKH) |
| 1 Tilt hinges bracket cushion / APC                         | \$ 60.00             | ✓ 5     |
| 1 Front RH headlamp lower apron / BR                        | \$ 70.00             | ✓ 5     |
| 1 Front SD garnish RH (Mirror garnish) / BR                 | \$ 95.00             | ✓ 5     |
| <del>1 Tilt hinge bracket LH ? X NN</del>                   | <del>\$ 150.00</del> |         |
| <del>1 Tilt hinge bracket cushion ? X NN</del>              | <del>\$ 60.00</del>  |         |
|                                                             | \$ 1,035.00          |         |
| Cost plus 10%                                               | \$ 103.50            |         |
|                                                             | \$ 1,138.50          |         |
| Labour to remove and refix dashboard to enable repair       | \$ 250.00            | 700     |
| Repair front dashboard                                      | \$ 250.00            | 700     |
| Labour to jacking front LH/RH chasis and RH/LH rod          | \$ 950.00            | 400 400 |
| Repair wiper-linkage bracket (and all other parts)          | \$ 250.00            | 100     |
| <del>X Remove and repair Hydraulic pipe with oil</del>      | <del>\$ 130.00</del> |         |
| Labour to remove/replace aircon blower and heater (gas) 2pc | \$ 250.00            | 100 150 |
| To repair air con pipe and repair to refricabe)             | \$ 250.00            | 150     |
|                                                             | \$ 3,598.50          |         |

\$825.00  
+10%  
Parts 907.50 ✓

Labour  
\$1050  
1330  
1150 ✓

grille 1480 -  
grille clip -  
wiper cap -  
no3 pipe

Labour to repair Heater assy - \$380

total - 2057.50



# CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,  
Spray-Painting, Mechanical Repair And Customizing of Cars  
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724  
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723  
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg  
Bus. Reg. No. 251513/00M

Policy No: DHOM120061152100  
DOA: 07/05/2022@1700


UNITED OVERSEA INSURANCE LTD 14.6.2022

ATTN: THE MOTOR CLAIMS DEPT

OD CLAIM  
ESTIMATE COST OF REPAIR FOR VEHICLE NO:  
GBL 3717 J - NISSAN CABSTAR SINGLE CAB MT  
CHASSIS NO: JN1SA2F24Z0000329 (06/2021)  
SUPPLEMENTARY

|                                                        |    |                     |                 |
|--------------------------------------------------------|----|---------------------|-----------------|
| Labour to repair HEATER assy.---photo taken (no stock) | \$ | 380.00              | 200 -           |
| Air con blower (complete)----photo taken BR (cost)     | \$ | 650.00              | +10%            |
| Labour to remove and replace aircon blower and heater  | \$ | 280.00              | 80 -            |
| To refill gas                                          |    | 650<br>+10%<br>715  |                 |
|                                                        |    | 400                 |                 |
|                                                        |    | total - 1115        |                 |
|                                                        | \$ | 120.00              | ✓               |
|                                                        | \$ | <del>1,430.00</del> | <del>1495</del> |

CHARN'S CUSTOMCRAFT



# CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,  
Spray-Painting, Mechanical Repair And Customizing of Cars  
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724  
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723  
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg  
Bus. Reg. No. 251513/00M

Policy No: DHOM120061152100  
DOA: 07/05/2022@1700

UNITED OVERSEA INSURANCE LTD

22.6.2022

ATTN: THE MOTOR CLAIMS DEPT

OD CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

GBL 3717 J - NISSAN CABSTAR SINGLE CAB MT

CHASSIS NO: JN1SA2F24Z0000329 (06/2021)

SUPPLEMENTARY 2

|                                   |             |
|-----------------------------------|-------------|
| Grille X NN                       | \$ 5.00 X   |
| Grille clip / NK                  | \$ 5.00 ✓   |
| Wiper arm cover / OR              | \$ 8.00 ✓   |
| Grille logo / NK                  | \$ 58.00 ✓  |
| Nosel connector (nose wiper) - OR | \$ 24.00 ✓  |
| Side mirror cover (RH) - NK       | \$ 19.00 ✓  |
| Radiator / BT                     | \$ 780.00 ✓ |
| Front panel sticker / NK          | \$ 60.00 ✓  |
|                                   | \$ 959.00   |
| Cost plus 10%                     | \$ 95.90    |
|                                   | \$ 1,054.90 |

total - 954  
+10%  
1049.40

Steve (LKK)  
29/6/22

CHARN'S CUSTOMCRAFT