

SKVTITU. 2015 August.

TPALG.

Mitsubishi Outlander 2360 cc

Xiao Long.

JMYXTGFBWGZU000761

Rees Bumper	Deformed	807	✓
Rees Bumper Clips.	new	30(SN)	✓
Rees Bumper Side Holder RH	2nd	28	✓
Rees Bumper Lower Garnish.	new	232	+
Rees RH Fender	Distorted	1114	✓
Rees RH Fender Inner Trim Board	new	796	+
Rees RH Fender Inner Trim Board Clips	new	30(SN)	+
Rees RH Fender Inner Shield	torn	89	✓
Rees RH Fender Inner Shield Clips.	new	30(SN)	✓
Rees RH Fender Arc Garnish.	Cut	179.	✓
Rees RH Fender Gloss Sealant.	new	60(SN)	✓
Rees RH Door	Dented	1088	✓
Rees RH Door Lock	Damaged	348.	✓
Rees RH Door Weatherstripe	Cut	168	✓
Rees RH Door Inner Trim Board	crushed	598	✓
Rees RH Door Inner Trim Board Clips	new	30(SN)	✓
Rees RH Door Black Tape.	New	50(SN)	✓

SKV717U.

Reer RH Door Glass Regulator Gear	AP	258.	X
Reer RH Door Protector	ut	205	/
Reer RH Door Protector Clips.	u	20(SN)	/
Rocker Panel RH	Revis	867.	X
Rocker Panel Outer Garnish	Behind	695	/
Rocker Panel Outer Garnish Clips.	u	30(SN)	/
Taillamp RH.	XHP u	506	/
Reer RH Wheel Rim.	ut	1650 700(SN)	
Reer RH Tyre	XHP u	350(SN)	X
Reer RH Lower Arm.	Bent	298	/
Reer RH Control Arm.		198	/
Reer RH Upper Arm.		228	/
Reer RH Knuckle Arm.	Bent	610.	/
Reer RH Wheel Hub c/w Bearing.	Bent	245	/
Reer RH Shock Absorber.	Bent	425	/
Reer Cross Member.	u u	1250	X

SKV717U.

Rear Exhaust Pipe	Dented	688	✓
Rear Exhaust Pipe Mounting	MPH	45	X
Rear Exhaust Pipe Gasket	MPH	38.	✓
- - -	8049	S.N. 940	
- - -	7244.10		

Panel Beating		1600	900.
Spray Painting.		1400	900.
Wiring.		100	30
To spray buff coat		150	60
To remove upholstery.		150	60.
To transfer rear door fittings.		150	80.
To remove rear fender g/s	2570	120	40
To remove rear exhaust pipe.		150	80
To remove rear undercarriage.		350	220
To perform wheel alignment.		150	80
Towing Charges (King Roller)		120	✓
		Total:	10754.10
		L/S:	8.61K 07 Days
		<u>8500</u>	