

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SKVTITU. 2015 August.

Mitsubishi Outlander 2360 cc

JMYXTGF3WGZ000761

Reas Bumper	Deformed	807 ✓
Reas Bumper Clips.	new	30(SN) ✓
Reas Bumper Side Holder RH	2nd	28 ✓
Reas Bumper Lower Garnish.	new	232 +
Reas RH Fender	Distorted	1114 ✓
Reas RH Fender Inner Trim Board	new	796 +
Reas RH Fender Inner Trim Board Clips	new	30(SN) +
Reas RH Fender Inner Shield	torn	89 ✓
Reas RH Fender Inner Shield Clips.	new	20(SN) ✓
Reas RH Fender Arc Garnish.	cut	179 ✓
Reas RH Fender Glass Sealant.	new	60(SN) ✓
Reas RH Door	Dented	1088 ✓
Reas RH Door Lock	Damaged	348 ✓
Reas RH Door Weatherstripe	cut	168 ✓
Reas RH Door Inner Trim Board	crushed	598 ✓
Reas RH Door Inner Trim Board Clips	new	30(SN) ✓
Reas RH Door Black Tape.	new	50(SN) ✓

SKV717U.

Reer RH Door Glass Regulator Gear	AP	258.	X
Reer RH Door Protector	ut	205	/
Reer RH Door Protector Clips.	u	20(SN)	/
Rocker Panel RH	Revis	867.	X
Rocker Panel Outer Garnish	Behind	695	/
Rocker Panel Outer Garnish Clips.	u	30(SN)	/
Taillamp RH.	XHP u	506	/
Reer RH Wheel Rim.	ut	1650 700(SN)	
Reer RH Tyre	XHP u	350(SN)	X
Reer RH Lower Arm.	Bent	298	/
Reer RH Control Arm.		198	/
Reer RH Upper Arm.		228	/
Reer RH Knuckle Arm.	Bent	610.	/
Reer RH Wheel Hub c/w Bearing.	Bent	245	/
Reer RH Shock Absorber.	Bent	425	/
Reer Cross Member.	u u	1250	X

SKV717U.

Rear Exhaust Pipe	Dented	688	✓
Rear Exhaust Pipe Mounting	MPH	45	X
Rear Exhaust Pipe Gasket	MPH	38.	✓
- - -	8049	S.N. 940	
- - -	7244.10		

Panel Beating	1600	900.
Spray Painting.	1400	900.
Wiring.	100	30
To spray buff coat	150	60
To remove upholstery.	150	60.
To transfer rear door fittings.	150	80.
To remove rear fender g/s	2570 120	40
To remove rear exhaust pipe.	150	80
To remove rear undercarriage.	350	220
To perform wheel alignment.	150	80
Towing Charges (King Roller)	120.	✓
	Total:	10754.10
	L/S:	8.61K 07 Days

8500