



PRIORITY SERVICES

INSURANCE LOSS ADJUSTERS AND MOTOR APPRAISERS

Block 779 Yishun Avenue 2 #01-1545 Singapore 760779
Tel: 6293 4822 Fax: 6296 3283

VEHICLE DAMAGE INSPECTION REPORT

Our File No: TP-0178/10/19
Date: 18/11/2019

REFERENCE

Handling Insurer: Sompoo Insurance Singapore Pte. Ltd. Policy No: D19MTMC01005756
Claimant Vehicle No: FBP3800E Insured Vehicle No: FBN1822R
Date of Loss: 19/10/2019 Nature of Claim: TP Claim No: CMTD1904973

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBP3800E**
Make & Model: HONDA CB400, 399cc Engine No: NC23E2066684
Reg. Date: 14/03/2005 (Man. Year: 2004) Chassis No: NC391056516
Colour: White/Blue Odometer: 11103 km
Engine Capacity: 399 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 120/60/R17 Rear Tyre Size: 120/60/R17
Front Left Side: 0 mm Rear Left Side: 0 mm
Front Right Side: Pirelli 5 mm Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 23/10/2019
Date Inspected: 30/10/2019 Inspected At: Equator Brotherhood (HQ)
25 kaki bukit rd 4 #03-79 synergy @ kb
Singapore 417800
Estimated Period of Repair: 0.0 days

Adjuster: Lawrence Ng
Surveyor

Manager: Sharon Kho
Administrator

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

PRE-REPAIR SURVEY

Date of Accident : 19-Oct-2019

Date and Time of Request : 23-Oct-2019 / 1.50pm

Date and Time of Inspection : 1) 30-Oct-2019 / 1.50pm (PRI by appointment)

2) 01-Nov-2019 / 11.50am (For dismantled items)

3) 05-Nov-2019 / 2.30pm (For after repair)

DOCUMENTS AVAILABLE AT TIME OF INSPECTION

1) T/P FBP 3800 E Singapore Accident Statement, Police Report & Accident Photos

VISUAL DAMAGES

At the rear portion.

Damages subject to consistency.

REMARKS

Despite our request, the repairer would not provide: -

1) Repairer estimate

Pre-Accident market value: About \$8,000.00.

COE Rebate: \$2,394.00 (COE expiry on 28-Feb-2025).

Estimated repair cost: About \$1,000.00.

Estimated period of repairs: About 2 working days.

REPAIR DETAILS

Reference

Part Source:		
Parts:	N/A	HONDA CB400 399cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Priority Services/FBP3800E/18/11/2019 14:19	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.		
Priority Services/FBP3800E/18/11/2019 14:19. Not valid without Reference section.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Priority Services/FBP3800E/18/11/2019 14:19. Not valid without Reference section.
--

< END OF ESTIMATES >