

PC2295Y. 2018 Dec

TP Budget Direct. Toyota Hiace Commuter. 2754cc
Xiao Chen. GDH2232001054.

Side Body Panel RH. Dented 1853.90. ✓

Side Body Inner Panel RH. Repair 1156.90. ✗

Side Body Panel G/433 Sealant. New ~~300(SN)~~ 200(SN) ✓

Excursion Bus Sticker New 30(SN) ✓

Rear Wheel Rim RH. New 280(SN) ✗

Rear Wheel Rim Cover RH. New ~~150(SN)~~ 120(SN)

Rear Wheel Hub clw Bearing. } 743.40 ✗

Rear Axle Housing } 2564.40 ✗

Rear Axle Shaft RH. } 1143.20 ✗

1853.90 S.N: 350.

1390.42

PC 22957

Panel Beating

Spray Painting

Wiring

To remove side panel g/s)

To spray tuff coat

To perform wheel alignment

To remove undercarriage

~~1000~~ 600

~~800~~ 800

~~50~~ 30

~~300~~ 200

~~200~~ 60

~~150~~ 80

1570

580.X

total: 3310.42

h/s: 2.6K.

04 Days

2.6K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: