



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2302857

INV Date 08/05/2023

Reference CC4/LPC22004583/Uya3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SGE 7272B
Insured Veh. GBC 5490X
Claim No. 21/22/22/VC00/025808
Policy No. Z/21/VC00/112072
Accident Date 16/05/2022
Inspection Date 18/05/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC22004583/Uya3q2 Date: 08/05/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 5490X	Veh. Inspected	SGE 7272B	
Policy No.	Z/21/VC00/112072	Coverage (\$)	0.00	
Claim No.	21/22/22/VC00/025808	Excess (\$)	0.00	
Assign From	CHARMAINE KONG	Assign Date	17/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI ATTRAGE (A)		c.c	1193
Engine No.	HIDDEN		Year of Reg.	2020
Chassis No.	MMBSTA13AMH000579		Colour	SILVER
Odometer	24915 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R15	BRIDGESTONE	7 mm	
L/H Front Tyre	185/55 R15	BRIDGESTONE	7 mm	
R/H Rear Tyre	185/55 R15	BRIDGESTONE	7 mm	
L/H Rear Tyre	185/55 R15	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.THE CHASSIS FRAME AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/05/2022	Inspection Date	18/05/2022	
Survey held at	JIN AUTO SERVICES PTE LTD BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGE 7272B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	BUCKLED	633.00	633.00
1	BONNET INSULATION	DISTORTED	160.00	160.00
1	BONNET LOCK	BENT	69.00	69.00
2	BONNET HINGE	BENT	100.00	100.00
1	WIPER GRILLE LH COVER	DISTORTED	28.00	28.00
1	L/F WING	BUCKLED	428.00	428.00
1	R/F WING EMBLEM	NOT NECESSARY	55.00	-
1	L/F WING EMBLEM	NOT NECESSARY	55.00	-
1	FRONT BUMPER	DISTORTED	703.00	703.00
2	FRONT BUMPER SIDE RETAINER	BENT	80.00	80.00
1	FOG LAMP LH	NOT NECESSARY	274.00	-
1	FOG LAMP RH	NOT NECESSARY	274.00	-
1	FOG LAMP COVER LH	NOT NECESSARY	47.00	-
1	FOG LAMP COVER RH	CUT	47.00	47.00
1	FRONT BUMPER TOW COVER	DISTORTED	20.00	20.00
1	FRT BMP CHROME LH	CRACKED	168.00	168.00
1	FRT BMP CHROME RH	CRACKED	168.00	168.00
1	FRT BMP CHROME CENTER	CRACKED	98.00	98.00
1	L/F HEADLAMP	CRACKED	2,088.00	1,706.00
1	R/F HEADLAMP	CRACKED	2,088.00	1,706.00
1	GRILLE	BROKEN	597.00	597.00
1	GRILLE BADGE	NECESSARY	60.00	60.00
1	GRILLE TOP PANEL	DISTORTED	130.00	130.00
1	FRONT PANEL CPL (SUPPORT PANEL)	BENT	1,000.00	918.00
1	SUPPORT PANEL AIR GUIDE	DISTORTED	36.00	36.00
1	RADIATOR	DISTORTED	872.00	872.00
1	RADIATOR FAN BLADE	BENT	80.00	77.00
1	RADIATOR FAN COWLING	CRACKED	160.00	160.00
1	RADIATOR FAN MOTOR	JAMMED	380.00	380.00
1	EXPANSION TANK	DISTORTED	38.00	38.00
1	AIRCON CONDENSER	BENT / PUNCTURE	683.00	683.00

Report Ref No. CC4/LPC22004583/Uya3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STEERING AIRBAG	ACTIVATED	900.00	600.00
1	SPIRAL CORD	ACTIVATED	350.00	255.00
1	AIRBAG ECU	ACTIVATED	650.00	650.00
1	DASHBOARD AIRBAG	ACTIVATED	1,501.00	1,501.00
2	SEATBELT ASSY	ACTIVATED	1,300.00	1,178.00
1	AIRCON LIQUID PIPE	NOT NECESSARY	220.00	-
1	AIRDUCT	CRACKED	120.00	120.00
1	SUPPORT PANEL TOP COVER	DISTORTED	130.00	130.00
1	RADIATOR TOP COVER	DISTORTED	110.00	110.00
1	AIRBAG SENSOR	ACTIVATED	12.00	12.00
2	AIRBAG L/R SENSOR	NO SUCH PARTS	240.00	-
1	AUTO COOLER JJ292A501A13A (ADDITIONAL)	DENTED	558.00	558.00
1	MANIFOLD (ADDITIONAL)	CRACKED	1,723.00	1,723.00
1	WIPER TANK (ADDITIONAL)	DEFORMED	77.00	77.00
1	LH WIPER SIDE GARNISH (ADDITIONAL)	REPEATED	28.00	-
1	BATTERY OUTER CASE (ADDITIONAL)	CRACKED	46.00	46.00
1	AIRCON SUCTION HOSE JJ7815A8888 (ADDITIONAL)	BENT	208.00	208.00
	LESS 10% DISCOUNT		-1,979.20	-1,723.30
			17,812.80	15,509.70
	<u>SPECIAL NETT ITEMS</u>			
10	FRONT BUMPER CLIPS (SN)	NECESSARY	40.00	40.00
10	REAR BUMPER CLIPS (SN)	NOT NECESSARY	40.00	-
1	FRONT NUMBER PLATE (SN)	BENT	50.00	40.00
			130.00	80.00
	<u>LABOUR</u>			
	TOWING.		80.00	60.00
	SPRAY PAINTING FRONT.		1,750.00	1,100.00
	LABOUR CHARGES FRONT.		1,250.00	1,000.00
	WIRING FRONT.		50.00	30.00
	TO REMOVE AND REFIX AIRCON PARTS REFILL GAS.		160.00	100.00
	TO REMOVE AND RENEW AIRBAG.		320.00	300.00
	REPROGRAMMING.		180.00	150.00

Report Ref No. CC4/LPC22004583/Uya3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFF KOTE.		100.00	80.00
			3,890.00	2,820.00
GRAND TOTAL			21,832.80	18,409.70
RECOMMENDED COST OF REPAIRS				18,409.70

Report Ref No. CC4/LPC22004583/Uya3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGE 7272B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGE 7272B

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGE 7272B

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

