



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22004590/Evy3m4	
			Date: 15/08/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SBS 6523U	Veh. Inspected	SNA 9050A
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22001474MFBP	Excess (\$)	0.00
	Assign From	HARMINDER KAUR	Assign Date	17/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ C180	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	WDD2050402R491152	Colour	BLACK
	Odometer	52007 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50 R17	MICHELIN	4 mm
	L/H Front Tyre	225/50 R17	MICHELIN	4 mm
	R/H Rear Tyre	225/50 R17	MICHELIN	4 mm
	L/H Rear Tyre	225/50 R17	MICHELIN	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/05/2022	Inspection Date	27/06/2022
	Survey held at	CYCLE & CARRIAGE INDUSTRIES PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	