

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SNA9050A Yr Regn: 3177/19Type: M.Cy / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes-Benz C180 c.c. 1595Colour: Black A/C: Insured / Std / Nil / NASp. Reading: 52007 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: WDD205042022491752Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/50R17R: 11BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 2x mmL/Bal. 1x mmD.O.A. 6/5/22Survey held at CUCN

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 1x mmL/Bal. 4 mmD.O.I. 27/6/22

Date / Time

Action / Instruction

MV-158K

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / I.B.F. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNA9050A

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information

WIP No 56838
Reg No/Reg Date SNA9050A / 31/07/2019
Date In/Mileage / 0
Chassis No WDD2050402R4911522
Engine No 27491031748294
Make/Model MB/MB C 180 AVANTGARDE/AVANTGARDE
Colour/Trim 021 197 Obsidian B1/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator			
WF001862	Credit	17/05/2022/ 10:56	AQ	305 / Alan Quek Ai Lun			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

M BPNSUN					
POLICY NO/ACC DATE : DMPCSNW00168482100 / 05-05-2022					
DRIVE IN: 14-05-2022 // TP CAR NO: SBS6523U (MS FIRST CAPITAL INS)					
DATE IN/DATE SURVEY:					
BY/AUTHORIZED ON :					
A BPILAB				0.10	380.00 ✓
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT					
A BPILAB					960 1440.00
REMOVE & REPLACE FRONT LEFT FENDER & REPAIR FRONT BUMPER					
A BPIRES				0.02	1600 2000.00
RESPRAY FRONT BUMPER & FRONT LEFT FENDER					
M LH/F FENDER		1.00	955.58	00.00	955.58

ESTIMATE

Steve CLKK)
27/6/22, 3:30pm

W L
PIP
hy PL
4 4

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part situation resurvey
- Part name

Authorized signatory and company stamp

	Nett	4,775.58
7% GST on	4775.58	334.29
Total Payable		5,109.87

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Date:

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

and Mercedes-Benz are trademarks of Mercedes-Benz Group AG