



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111-X

ESTIMATE FOR SNA9050A

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

WIP No
Reg No/Reg Date
Date In/Mileage
Chassis No
Engine No
Make/Model
Colour/Trim

Vehicle & Document Information

56838
SNA9050A / 31/07/2019
WDD2050402R4911522
27491031748294
MB/MB C 180 AVANTGARDE/AVANTGARDE
021 197 Obsidian Bl/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WF001862	Credit	17/05/2022/ 10:56	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services								

M BPNSUN
POLICY NO/ACC DATE : DMPCSNW00168482100 / 05-05-2022
DRIVE IN: 14-05-2022 // TP CAR NO: SBS6523U (MS FIRST CAPITAL INS)
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :
A BPILAB
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NETT
A BPILAB
REMOVE & REPLACE FRONT LEFT FENDER & REPAIR FRONT BUMPER
A BPIRES
RESPRAY FRONT BUMPER & FRONT LEFT FENDER
M LH/F FENDER

0.10 380.00
0.02 1440.00
0.02 2000.00
1.00 955.58 00.00 955.58

ESTIMATE

Steve CLKK)
27/6/22, 3:37pm

W L
PIP
by BL 17
4 4

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
OID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

4797.57

Confirmed & accepted by
the Repairer of the following:
• To survey before spray painting
• To spray damaged parts
• To repair damaged parts

Authorized signatory and company stamp

7% GST on Nett 4,775.58 334.29
Total Payable 5,109.87

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Date:

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg