



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNA9050A

Finalization

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Steve

Vehicle & Document Information

WIP No 56838
Reg No/Reg Date SNA9050A / 31/07/2019
Date In/Mileage 27/06/2022 / 52007
Chassis No WDD2050402R4911522
Engine No 27491031748294
Make/Model MB/MB C 180 AVANTGARDE/AVANTGARDE
Colour/Trim 021 197 Obsidian B1/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	05/08/2022/ 11:58	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : DMPCS NW00168482100 // 05-05-2022 DRIVE IN: 14-05-2022 // TP CAR NO: SBS6523U (MS FIRST CAPITAL INS) DATE IN/DATE SURVEY: 27-06-2022 // LKK STEVE BY/AUTHORIZED ON : ESTHER LIM // 19-05-2022				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
A BPILAB REMOVE & REPLACE FRONT LEFT FENDER & REPAIR FRONT BUMPER				960.00
A BPIRES RESPRAY FRONT BUMPER & FRONT LEFT FENDER			0.05	1600.00
X LH/F FENDER	1.00	977.57	00.00	977.57

4 Days

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

7% GST on 3917.57
Nett 3,917.57
274.23

Authorized signatory and company stamp

Total Payable 4,191.80

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg