



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNA9050A

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information

WIP No **56838**
Reg No/Reg Date **SNA9050A / 31/07/2019**
Date In/Mileage **/ 0**
Chassis No **WDD2050402R4911522**
Engine No **27491031748294**
Make/Model **MB/MB C 180 AVANTGARDE/AVANTGARDE**
Colour/Trim **021 197 Obsidian Bl/ 041 101 ARTICO Blac**

Account No	Terms	Date/Time Printed	CSE	Operator	
WF001862	Credit	17/05/2022/ 10:56	AQ	305 / Alan Quek Ai Lun	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

M BPNSUN
POLICY NO/ACC DATE : DMPCSNW00168482100 / 05-05-2022
DRIVE IN: 14-05-2022 // TP CAR NO: SBS6523U (MS FIRST CAPITAL INS)
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB		0.10			380.00
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT					
A BPILAB					1440.00
REMOVE & REPLACE FRONT LEFT FENDER & REPAIR FRONT BUMPER					
A BPIRES		0.02			2000.00
RESPRAY FRONT BUMPER & FRONT LEFT FENDER					
M LH/F FENDER	1.00	955.58	00.00		955.58

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett **4,775.58**
7% GST on **4775.58** **334.29**
Total Payable 5,109.87

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG