



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22004592/Rvy3e2 Date: 27/05/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMB 3578R	Veh. Inspected	SMB 50R
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/05/22/5018	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	17/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ OC500LE1830H	c.c	11967
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	WEB63442021000122	Colour	GREEN
	Odometer	201549 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	275/70 R22.5	MICHELIN	8 mm
	L/H Front Tyre	275/70 R22.5	MICHELIN	8 mm
	R/H Rear Tyre	275/70 R22.5 (D)	MICHELIN	8/8 mm
	L/H Rear Tyre	275/70 R22.5 (D)	MICHELIN	8/8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	12/05/2022	Inspection Date	18/05/2022
	Survey held at	310 MANDAI RD S 779404		
	Repairer	TOWER TRANSIT SINGAPORE PTE. LTD.		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	