

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

L		Affiliated to Federation Internationale Des Experts En Automobile					
	JNITED OVERSEA	AS INSURANCE LTD	F	Ref:	CS/UOI22004595/Kqy3e2		
	46 ROBINSON RO 02-01 UOI BUILDI	С	Date:	15/06/2022			
			C	Code:	UOI2		
1.	Policy Particulars :- THIRD PARTY CLAIM						
lı lı	nsured Veh.	SLF 3075R	Veh. Inspected		SMS 6725Z		
F	Policy No.		Coverage (\$)		0.00		
	Claim No.	M12D18092204	Excess (\$)		0.00		
<i>P</i>	Assign From	JOSEPHINE WONG	Assign Date		17/05/2022		
2. Vehicle Particulars & Condition							
N	Make & Model	TOYOTA PRIUS (A)	c.c		1798		
E	Engine No.	HIDDEN	Year of Reg.		2020		
C	Chassis No.	JTDKB3FU303091052	Colour		METALLIC SILVER		
	Odometer	162585 KM	Steering		IN ORDER		
E	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM		
	General	GOOD					
3. Conditions of Tyres							
		Size	Make		Balance		
F	R/H Front Tyre	195/65 R15	LANVIGATOR		9 mm		
L	_/H Front Tyre	195/65 R15	LANVIGATOR		9 mm		
F	R/H Rear Tyre	195/65 R15	SAILUN		2 mm		
L	_/H Rear Tyre	195/65 R15	SAILUN		2 mm		
4.	. Description of Damages						
Т	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.						
	DAMAGES SEE DETAILS.						
5.	General Information						
A	Accident Date	22/03/2022	Inspection Date		18/05/2022		
S	Survey held at	TRANS-CAB AUTO SERVICES	PTE LTD				
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111					
5a.	Remarks						
A	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b.	Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days						