

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHC7197J

Make : HYUNDAI

Model : I-40

Date: 17/05/2022

Insurance: ECICS

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	RR FENDER RH <i>X Repair</i>			\$ 2,171.40	
1	REAR BUMPER <i>X</i>			\$ 553.00	
10	RR BUMPER CLIPS <i>X NN</i>			\$ 22.00	
1	RR WHEEL HUB CAP RH <i>/ Cut</i>			\$ 214.20	
	SUB TOTAL			\$ 2,960.60	
	LESS 20%			\$ 592.12	
	DISCOUNTED TOTAL			\$ 2,368.48	
	RR DOOR COMFORT APP LOGO <i>/ MLC</i>		-10%	\$ 80.00	Nett
				\$ 80.00	Nett
	Labour Charge				
	PANEL BEATING			\$ 1,000.00	<i>350 280</i>
	SPRAY PAINTING CHARGE			\$ 800.00	<i>750</i>
	REMOVE/ REFIX UPHOLSTERY & CUSHION RR			\$ 120.00	
	TUFF KOTE			\$ 60.00	<i>X NN</i>
	TOTAL LABOUR			\$ 1,980.00	
	ESTIMATE TOTAL			\$ 4,428.48	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

*2 Days.**P/P**After repair photos.**Gmo Qr p**17/5/22**3:30pm***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged on test up to resurvey
- Parts prices to be on "market price" basis
- Third party to be on "market price" basis
- No illegal work to be done
- Supplier to be on "market price" basis and is subject to final approval from Insurance Company

Acknowledged by, Repaired:

Signature:

Date: