

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHC7197J

Make : HYUNDAI

Model : I-40

Date: 17/05/2022

Insurance: ECICS

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	RR FENDER RH <i>X Repair</i>			\$ 2,171.40	
1	REAR BUMPER <i>X</i>			\$ 553.00	
10	RR BUMPER CLIPS <i>X NN</i>			\$ 22.00	
1	RR WHEEL HUB CAP RH <i>/ Cut</i>			\$ 214.20	✓
SUB TOTAL				\$ 2,960.60	
LESS 20%				\$ 592.12	
DISCOUNTED TOTAL				\$ 2,368.48	171.36
RR DOOR COMFORT APP LOGO <i>/ MCL</i>				-10% \$ 80.00	Nett
				\$ 80.00	Nett 72
Labour Charge					
PANEL BEATING				\$ 1,000.00	350 280
SPRAY PAINTING CHARGE				\$ 800.00	750
REMOVE/ REFIX UPHOLSTERY & CUSHION RR				\$ 120.00	
TUFF KOTE				\$ 60.00	<i>X Snn</i>
TOTAL LABOUR				\$ 1,980.00	
ESTIMATE TOTAL				\$ 4,428.48	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

1273.76

-20%: 1000

2 Days.
P/P
 After repair photos.
 Gmo Qw p
 17/5/22
 3:30pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) after resurvey
- Parts prices to be based on "market price"
- Third party to be based on "insurance" basis
- No illegal work to be carried out
- Supplier to be approved and is subject to final approval from Insurance Company

Acknowledged by, Repaired:

Signature:

Date: