

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/TP/0403/2022/JT  
DATE : 18-May-22  
WIP : 24436

Veron.

\$6131.

03 Days.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 24/5/22  
YOUR INSURED VEH NO : SHF 179 S

MS FIRST CAPITAL INSURANCE Ltd  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877  
Attn: Motor Claims Dept  
Tel: 6854 3909 - Fax: 6507 3849

OWNER'S NAME : MR LEE JINGLEONG  
ADDRESS : 89 ROSEWOOD DRIVE  
#03-95  
SINGAPORE 737792  
TELEPHONE : HP +65 91996409  
TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : CA582022/1  
VEHICLE NO : SMZ 6888 A  
MODEL CODE : AUDI Q3 5B 1.4 TFSI  
MODEL YEAR : 13/10/2020  
ENGINE NO : CZD C06668  
CHASSIS NO : WAUZZZF31M1013064  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 15-May-22  
PLACE OF ACCIDENT : BUKIT BATOK WEST AVE 6

# **PREMIUM AUTOMOBILES**

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA.KHA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



## **ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 6888 A**

| S/N                         | NATURE OF JOBS                                                                                                                          | ESTIMATED CHARGES    | SURVEYOR'S RECOMMENDATIONS                 |
|-----------------------------|-----------------------------------------------------------------------------------------------------------------------------------------|----------------------|--------------------------------------------|
| 1                           | TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LTD KICK SENSOR.                                                                       | S/N \$ 360.00        | ✓                                          |
| 2                           | TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ 1,600.00          | ✓ Spoiler 300                              |
| 3                           | TO RESPRAY REAR BUMPER, REAR END PANELLING AND BOTH REAR WHEEL ARCH TRIMS.                                                              | \$ 3,000.00          | 2200 1400 Bumper 200 Wheel Arch x 2 = 1000 |
| 4                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                          | S/N \$ 192.00        | ✓ 2200                                     |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                         | <b>: \$ 5,152.00</b> |                                            |

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL: 6366 2323 FAX: 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SSMZ 6888 A

|                      |                                                     | DAMAGED PARTS & PRICES |              |         |
|----------------------|-----------------------------------------------------|------------------------|--------------|---------|
| S/N                  | PARTS DESCRIPTION                                   | QTY                    | S/NETT       | REMARKS |
| 1                    | REAR BUMPER <i>3xRhd</i>                            | 1                      | \$ 1,738.00  | ✓ 1738  |
| 2                    | REAR BUMPER SPOILER                                 | 1                      | \$ 510.00    | ✓ 510   |
| 3                    | REAR BUMPER GRILLE - RH                             | 1                      | \$ 170.00    | +       |
| 4                    | REAR PARKING AID SENSOR SUPPORT - RH <i>3xRhd</i>   | 1                      | \$ 28.00     | +       |
| 5                    | REAR BUMPER ADAPTER - LH / RH                       | 2                      | \$ 190.00    | +       |
| 6                    | REAR BUMPER CROSS REINFORCEMENT - CENTER <i>new</i> | 1                      | \$ 108.00    | +       |
| 7                    | REAR BUMPER BRACKET                                 | 1                      | \$ 53.00     | +       |
| 8                    | REAR LIGHT REFLECTOR - RH <i>new</i>                | 1                      | \$ 46.00     | +       |
| 9                    | BOOT LID CONTROL UNIT                               | 1                      | \$ 454.00    | +       |
| 10                   | TAILGATE SENSOR LINE                                | 1                      | \$ 228.00    | +       |
| 11                   | REAR BUMPER SHOCK ABSORBER <i>new</i>               | 1                      | \$ 95.00     | +       |
| 12                   | REAR BUMPER REINFORCEMENT <i>Not new</i>            | 1                      | \$ 693.00    | ✓ X     |
| 13                   | REAR BUMPER HOLDING STRAP - LH / RH <i>Not new</i>  | 2                      | \$ 64.00     | ✓ X     |
| 14                   | REAR PARKING AID SENSOR <i>3xRhd</i>                | 3                      | \$ 795.00    | +       |
| 15                   | REAR PARKING AID SENSOR SEAL RING <i>new</i>        | 4                      | \$ 10.00     | +       |
| 16                   | REAR BUMPER WIRING SET                              | 1                      | \$ 449.00    | +       |
| 17                   | REAR WHEEL ARCH COVER - LH / RH <i>new</i>          | 2                      | \$ 1,132.00  | ✓ 1131  |
| 18                   | UNDERBODY TRIM - RH <i>Not new</i>                  | 1                      | \$ 58.00     | +       |
| 19                   | SUNDRIES <i>Not new</i>                             |                        | \$ 300.00    | ✓ X     |
| TOTAL SPARE PARTS    |                                                     | :                      | \$ 7,121.00  |         |
| TOTAL LABOUR CHARGES |                                                     | :                      | \$ 5,152.00  |         |
| GRAND TOTAL          |                                                     | :                      | \$ 12,273.00 |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

: Adnan

SURVEYED DATE

: 24/05/22

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

: Not Insured, 03 Days H.S.

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: