

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/TP/0403/2022/JT  
**DATE** : 18-May-22  
**WIP** : 24436

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 24/5/22**

**YOUR INSURED VEH NO : SHF 179 S**

**MS FIRST CAPITAL INSURANCE Ltd**

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

Attn: Motor Claims Dept

**Tel: 6854 3909 - Fax: 6507 3849**

**Hi Adrian,**

**3 days - ok - Jy - 12 Aug 22**

**OWNER'S NAME** : MR LEE JINGLEONG  
**ADDRESS** : 89 ROSEWOOD DRIVE  
#03-95  
SINGAPORE 737792  
**TELEPHONE** : HP +65 91996409  
**TYPE OF CLAIM** : THIRD PARTY CLAIM  
**POLICY NO** : GA582022/1  
**VEHICLE NO** : **SMZ 6888 A**  
**MODEL CODE** : AUDI Q3 SB 1.4 TFSI  
**MODEL YEAR** : 13/10/2020  
**ENGINE NO** : CZD C06668  
**CHASSIS NO** : WAUZZZF31M1013064  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 15-May-22  
**PLACE OF ACCIDENT** : BUKIT BATOK WEST AVE 6

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 6888 A**

| S/N                         | NATURE OF JOBS                                                                                                                          |        | ESTIMATED<br>CHARGES |    | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|-----------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|----|-------------------------------|
| 1                           | TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.                                                                       | S/N \$ | 360.00               | \$ | 360.00                        |
| 2                           | TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$     | 1,600.00             | \$ | 800.00                        |
| 3                           | TO RESPRAY REAR BUMPER, REAR END PANELLING AND BOTH REAR WHEEL ARCH TRIMS.                                                              | \$     | 3,000.00             | \$ | 1,400.00                      |
| 4                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                          | S/N \$ | 192.00               | \$ | 192.00                        |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                         | :      | <b>\$ 5,152.00</b>   | \$ | <b>2,752.00</b>               |

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SSMZ 6888 A**

|                             |                                          |     | DAMAGED PARTS & PRICES |                    |
|-----------------------------|------------------------------------------|-----|------------------------|--------------------|
| S/N                         | PARTS DESCRIPTION                        | QTY | S/NETT                 | REMARKS            |
| 1                           | REAR BUMPER                              | 1   | \$ 1,738.00            | \$ 1,738.00        |
| 2                           | REAR BUMPER SPOILER                      | 1   | \$ 510.00              | \$ 510.00          |
| 3                           | REAR BUMPER GRILLE - RH                  | 1   | \$ 170.00              |                    |
| 4                           | REAR PARKING AID SENSOR SUPPORT - RH     | 1   | \$ 28.00               |                    |
| 5                           | REAR BUMPER ADAPTER - LH / RH            | 2   | \$ 190.00              |                    |
| 6                           | REAR BUMPER CROSS REINFORCEMENT - CENTER | 1   | \$ 108.00              |                    |
| 7                           | REAR BUMPER BRACKET                      | 1   | \$ 53.00               |                    |
| 8                           | REAR LIGHT REFLECTOR - RH                | 1   | \$ 46.00               |                    |
| 9                           | BOOT LID CONTROL UNIT                    | 1   | \$ 454.00              |                    |
| 10                          | TAILGATE SENSOR LINE                     | 1   | \$ 228.00              |                    |
| 11                          | REAR BUMPER SHOCK ABSORBER               | 1   | \$ 95.00               |                    |
| 12                          | REAR BUMPER REINFORCEMENT                | 1   | \$ 693.00              |                    |
| 13                          | REAR BUMPER HOLDING STRAP - LH / RH      | 2   | \$ 64.00               |                    |
| 14                          | REAR PARKING AID SENSOR                  | 3   | \$ 795.00              |                    |
| 15                          | REAR PARKING AID SENSOR SEAL RING        | 4   | \$ 10.00               |                    |
| 16                          | REAR BUMPER WIRING SET                   | 1   | \$ 449.00              |                    |
| 17                          | REAR WHEEL ARCH COVER -LH / RH           | 2   | \$ 1,132.00            | \$ 1,131.00        |
| 18                          | UNDERBODY TRIM - RH                      | 1   | \$ 58.00               |                    |
| 19                          | SUNDRIES                                 |     | \$ 300.00              |                    |
| <b>TOTAL SPARE PARTS</b>    |                                          | :   | <b>\$ 7,121.00</b>     | <b>\$ 3,379.00</b> |
| <b>TOTAL LABOUR CHARGES</b> |                                          | :   | <b>\$ 5,152.00</b>     | <b>\$ 2,752.00</b> |
| <b>GRAND TOTAL</b>          |                                          | :   | <b>\$ 12,273.00</b>    | <b>\$ 6,131.00</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.  
 bl-02/08/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :  
SURVEYED DATE :  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF  
THE AFFECTED VEHICLE. SHOULD WE REQUIRE  
FURTHER LABOUR CHARGES AND SPARE PARTS IN THE  
PROGRESS OF REPAIR, WE SHALL INFORM YOU  
ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO  
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR  
APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT