

REPAIR ESTIMATE

Time: 16:22:30 Juman
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305513822
 REGN NO : SHA5092B
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 15.12.2016
 DATE/TIME IN : 25.04.2022 13:00
 ACCIDENT DATE : 24.04.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	553.00	20.00	442.40	/Cut
0002 04-01-0103-0738-G	COVER-RR BUMPER LWR#	1	228.00	20.00	182.40	/Cut
0003 04-01-0103-0739-G	ABSORBER-RR BUMPER ENERGY	1	119.50	20.00	95.60	X M Svc
0004 04-01-0103-0740-G	DEP BEAM-RR BUMPER#	1	428.40	20.00	342.72	X Svc
0005 04-01-0103-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	/MC
0006 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	/MC
0007 09-01-9999-0068-A	REVERSE SENSOR ASSY*	1	135.70	10.00	122.13	/Cut

SUB-TOTAL : 1,252.85

JOB NATURE

0000 PB	PANEL BEATING	400.00	3500	280
0001 SP	SPRAYPAINT CHARGE	300.00	250	
0002 L	REMOVE/REFIX REVERSE SENSOR	50.00	30	

SUB-TOTAL : 750.00

F: 1100
 RD: 2

Thyon
 82235769
 24/4/22
 S
 1645
 2 day sup

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer