

## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SH9519U

Make : HYUNDAI

Model : IONIQ(G3)

Date: 26.04.2022

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER			\$ 481.10
10	FRT BUMPER CLIPS			\$ 22.00
1	FRT BUMPER SIDE BRACKET LH			\$ 28.00
1	FRT BUMPER BRACKET TOP LH			\$ 35.00
1	FRT BUMPER CENTRE MOULDING UPPER			\$ 368.50
1	FRT BUMPER MOULDING LH			\$ 93.60
1	FRT BUMPER LOWER GRILLE			\$ 186.90
1	RADIATOR GRILLE			\$ 1,409.10
1	HEADLAMP SUPPORT PANEL ASSY			\$ 949.30
1	DAY LIGHT LH			\$ 642.50
1	HEADLAMP LH			\$ 2,110.30
1	FRT BUMPER REINFORCEMENT			\$ 1,136.70
1	FRT BUMPER LIP			\$ 35.10
1	FRT LOWER GRILLE MOULDING			\$ 186.90
1	FRT BUMPER SPONGE			\$ 186.90
	<b>SUB TOTAL</b>			\$ 7,871.90
	<b>LESS 20%</b>			\$ 948.13
	<b>DISCOUNTED TOTAL</b>			\$ 6,923.77
				nett
	<b>Labour Charge</b>			
	PANEL BEATING			\$ 800.00
	SPRAY PAINTING CHARGE			\$ 300.00
	TUFF KOTE			\$ 60.00
	CHECK LIGHTING / WIRING			\$ 60.00
	<b>TOTAL LABOUR</b>			\$ 1,220.00
	<b>ESTIMATE TOTAL</b>			\$ 8,143.77

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sup: Number plate / cra

Thuan

87235769

26/4/22 1700

L18 7days

P/P

F: 2444.76

RO: 2