

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22004639/Gqy3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 26/05/2022 SINGAPORE 068811 ATTN: TEO KITTY Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHD 3664Z CB 7266H Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S2M0412W Excess (\$) 0.00 **TEO KITTY** 18/05/2022 Assign From Assign Date 2. **Vehicle Particulars & Condition** TOYOTA / HIACE COMMUTER | c.c Make & Model 2982 2013 HIDDEN Engine No. Year of Reg. KDH2230017328 SILVER Chassis No. Colour Odometer 393205 KM Steering **IN ORDER IN ORDER** NIL **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195R15 **MICHELIN** 6 mm L/H Front Tyre 195R15 **MICHELIN** 6 mm **MICHELIN** R/H Rear Tyre 195R15 6 mm L/H Rear Tyre 195R15 **MICHELIN** 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 11/05/2022 18/05/2022 (12:15 PM) Inspect Date / Time Accident Date M.S LLH Survey held at 1, KAKI BUKIT AVENUE 6 #01-67 AUTOBAY@KAKI BUKIT SINGAPORE 417883 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000 5b. **Estimate Days of Repair**

Report Ref No. CS3/ASM22004639/Gqy3e2

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

5 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.