

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : YN9007C
Accident Date : 13-May-2022

No. : 06587

Date : 17-May-2022

Our Ref : 022080 (FIRST) / CHAN

PAGE : 1

LIM KENG TEIK GARY
38 ANDREWS TERRACE
Singapore 757652

*Not Notation
11Rm 80250/h
Mummy After Point
-3 days*

ESTIMATED COST OF REPAIR FOR NISSAN GTR SDS4333R

1 pc Rear bumper fascia
1 pc Rear bumper lower spoiler
1 pc Rear bumper lower grille
1 pc Rear bumper "GTR" emblem
1 pc Rear bumper reinforcement
1 pc Rear no.plate
1 pc Rear bumper reverse camera
"bumper Spoiler" CMA 264.20SN

R 3,816.00 SN ✓
CMA 1,272.00 SN ✓
P 804.50 SN ✓
M 214.40 SN ✓
AT 1,252.00 SN ✓
CMA 264.20 SN ✓
SN 300.00 SN ✓
400.00 300

To putty and spray replaced parts

500.00 25d

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

Total : S\$ 8,598.90

Singapore Dollars Eight Thousand Five Hundred
and Ninety Eight and Cents Ninety Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: