

Not Authorized

llll
urrah

18/5/22

h/s \$3400

the repairer
3 days.



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AlGAsia Insured's Veh No : SNC9165S

Date of Accident : 11 May 2022

Miss Kathleen Chia Bee Ling (Kathleen Xie Meiling)

Date : 18 May 2022

Estimate To Repair SGC37X - Lexus ES350H Hybrid

Chassis No : JTHBW1GG902060961

S/No	Quantity	Description	Amount
		<u>NET ITEMS</u>	
01	1 pc	bootlid	\$ 1,143.70
02	1 pc	bootlid lock	\$ 472.00
03	1 pc	bootlid Lexus badge	\$ 173.70
04	1 pc	bootlid ES300h badge	\$ 75.00
05	1 pc	bootlid emblem badge	\$ 66.90
06	1 pc	bootlid weatherstrip	\$ 226.00
07	1 pc	rear bumper	\$ 999.00
08	1 pc	rear bumper reinforcement	\$ 621.00
09	2 ps	rear bumper bracket @ \$65.00	\$ 130.00
10	2 ps	rear bumper side retainer @ \$137.30	\$ 274.60
11	1 pc	rear bumper sponge	\$ 120.00
12	4 ps	rear bumper parking sensor @ \$473.30	\$ 1,893.20
13	2 ps	rear bumper reflector @ \$60.00	\$ 120.00
14	1 pc	rear end panel	\$ 752.00
15	1 pc	rear end panel inner trim	\$ 296.20
		Less 10 %	\$ 7,363.30 \$ 736.33
			\$ 6,626.97
		<u>LABOUR & MISC. CHARGES</u>	
01		To reinstall of rear bumper parking sensor.	\$ 120.00
02		To check electrical lighting concerned.	\$ 60.00
03		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 120.00
04		To rust-proofing of the affected areas.	\$ 200.00
05		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 100.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 900.00
07		Putty and spray painting of the affected portion.	\$ 1,000.00
			\$ 2,500.00
		Total	\$ 9,126.97

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1 - 3433.7
102
3090.33
1220
4310.33