

**AUTOWERKS****ZOOM AUTOWERKS PTE LTD**

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

19 May 2022

REG NO.: SMQ 7015 T
MAKE/MODEL: HYUNDAI AVANTE

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
LIST ITEMS		
1	Front headlamp -RH	\$ 11 3,034.90 X
1	Front headlamp lower bracket -RH	\$ 11 127.60 X
1	Front grille	\$ 11 628.60 X
1	Front grille chrome moulding	\$ 11 180.80 X
1	Front grille logo	\$ 11 91.00 X
1	Front bumper	\$ cut/100m 474.40 ✓
1	Front bumper fog lamp	\$ 11 200.30 X
1	Front bumper fog lamp grille	\$ 11 150.20 X
1	Front bumper inner sponge	\$ 11 150.50 X
1	Front bumper lower moulding	\$ 11 288.90 X
1	Front bumper reinforcement	\$ 11 695.80 X
1	Front bumper side retainer	\$ 02 60.20 ✓
1	Front bumper top rubber	\$ 11 65.00 X
1	Front bumper lower beam	\$ 11 265.00 X
1	Front fender -RH	\$ 500 677.30 ✓
1	Front fender inner shield	\$ 11 120.80 X
1	Front fender stay	\$ 11 120.30 X
1	Front mudflap	\$ 11 115.20 ✓
1	Front wheel hub	\$ 500 189.50 ✓
1	Front wheel bearing	\$ 200 155.80 ✓
1	Front shock absorber	\$ 11 424.50 X
1	Front knuckle arm	\$ 500 455.80 ✓
1	Front door -RH	\$ R 1,831.20 X
		\$ 10,503.60
	Less 20%	\$ 2,100.72
		\$ 8,402.88

SPECIAL NETT ITEMS

1	Front bumper clip (1 set)	\$	111	80.00	50
1	Front fender inner shield clip (1 set)	\$	111	65.00	X
1	Front tyre	\$	811	400.00	X
1	Front wheel rim -RH	\$	511	850.00	650
		\$		1,395.00	

S/N

LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$	80.00	20
2	To remove and refit front undercarriage.	\$	300.00	120
3	To conduct wheel alignment.	\$	180.00	100
4	To apply undercoating.	\$	200.00	30
5	Panel beating.	\$	1,600.00	500
6	To re-spray painting on the affected areas.	\$	1,500.00	500
		\$	3,860.00	

GRAND TOTAL :

\$ 13,657.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2128-2
252
1702-58
700
1370
3772-58