

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21012657/T1ty3e2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER 17/01/2022 Date: SINGAPORE 068811 ATTN: LOH CYNTHIA Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHA 5750K Veh. Inspected 5431S Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S1M03O1W Excess (\$) 0.00 **LOH CYNTHIA Assign Date** 14/12/2021 Assign From **Vehicle Particulars & Condition** 2. MITSUBISHI EVO c.c 0 Make & Model HIDDEN Engine No. Year of Reg. WHITE Chassis No. Colour Odometer 116992 KM Steering IN ORDER **IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 245/40 R18 NEXEN 6 mm 245/40 R18 NEXEN L/H Front Tyre 6 mm 245/40 R18 NEXEN R/H Rear Tyre 6 mm **NEXEN** L/H Rear Tyre 245/40 R18 6 mm **Description of Damages** 4. THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. 5. **General Information** 08/12/2021 17/12/2021 (01:30 PM) **Accident Date** Inspect Date / Time 160 Sin Ming Drive #05-18, Sin Ming Autocity Survey held at Repairer CARFEELS PTE LTD 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500-\$4,500

Report Ref No. CS3/ASM21012657/T1ty3e2

Estimate Days of Repair

Inspected By

5b.

MOHAMAD TAUFIKH

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

5 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser

M.MATAI, AMSAE-A
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.