

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Allianz Global Corporate & Specialty SE, Singapore Branch

Policy No: SPMF1000000449

Date: 14.05.2022

Accident Date : 05.05.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Kia Cerato" Reg. No SMJ2660A		
1pc	Front Bumper	1.50	285.00 / Cut
1pc	Front Bumper Clips		18.00 / nec
1pc	Front Bumper Bracket RH		12.00 / nec
1pc	Front Bumper Sponge		115.00 ? - Cut
1pc	Front Bumper Reinforcement		190.00 ? - DT
1pc	Front Bumper Beam		DT - 50.00 ? - 80.00
1pc	Front Bumper Emblem		20.00 / nec
1pc	Front Bumper Corner Retainer RH		12.00 / nec
1pc	Front Bumper Signal Lamp RH		80.00 / 100.00 / Cra
1pc	Front Bumper Side Air Grille RH		8.00 / Cut
1pc	Front Bumper Lower Lip		130.00 / Cut
1pc	Front Bumper Lower Lip Garnish		60.00 / Cra
1pc	Front Bumper Fog Lamp RH		120.00 / Cra
1pc	Front Bumper Air Duct RH		10.00 / Cut
1pc	Headlamp RH		530.00 x Svc
1pc	Headlamp Lower Bracket		35.00 / Cut
1pc	Grille		130.00 / Cut
1pc	Front Fender RH		160.00 / DT
1pc	Front Fender Shield		58.00 x Svc
1pc	Wiper Tank		65.00 x Svc
1pc	Wiper Tank Motor		45.00 x Svc
1pc	Support Panel		325.00 ? - Br
1pc	Front Wheel Rim		350.00 / Scr
1pc	Front Shock Absorber		115.00 x Svc
1pc	Front Knuckle Arm		130.00 x Svc
1pc	Front Knuckle Arm Bearing		180.00 x Svc
1pc	Front Lower Arm		125.00 x Svc
	Cost Plus 10%	1986 2178	3,358.00 335.80 3,693.80
	To Conduct Electrical Check, Focus Headlamp		30.00 / 20
	To Remove / Refit Air Con Condenser & Refill Air Con Gas		120.00 x NN
	To Remove / Refit, Radiator System, Bleed, Refill Coolant		60.00 x NN
	To Dismantle / Replace Front Under Carriage to Facilitate Repair		180.00 x NN
		C/F	4,083.80

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: Z21880/00C GST Reg. No: MX-0486007-A0

To: Allianz Global Corporate & Specialty SE, Singapore Branch

Policy No: SPMF1000000449

Date: 14.05.2022

Accident Date : 05.05.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Kia Cerato" Reg. No SMJ2660A		
		B/F	4,083.80
	To Conduct Computerize Wheel Alignment Test		80.00 XNN
	Labour Charge - Panel Beating, Repairing of Bonnet, Front Chassis, Front Fender Inner Panel & Part Replacement		700.00 400 600
	To Respray Affected Areas		650.00 600
		Total :	<u>5,513.80</u>
Thuan@Chhauto.com 82235769 18/5/22 1730 OP not authorise L/S repair slays wp F: 2700 RP: 5			
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer			