



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX : *Permy B4pam*

ATTN :

YOUR REF NO : GBD2314L

CLAIM TYPE : THIRD PARTY

TP INS. CO. : LONPAC INSURANCE BHD

ACCIDENT DATE : 30/04/2022

TP VEH REG NO : GBD2314L

ESTIMATE

NO : QUOT202205-000044(00)

DATE : 18/05/2022

POLICY NO : 999995580

VEH REG NO : GBF5485X

MAKE/MODEL : TOYOTA HIACE VAN TURBO 5
DR

CHASSIS NO : JTFHT02P900209071

ENGINE NO : 1KD2660715

REG. DATE : 2016

Estimate Repair Cost to Vehicle No : GBF5485X

Description	Quantity	Unit Price	Amount
		S\$	S\$
LIST PRICE			
1 Tailgate <i>2168.50</i>	1	2,168.50	2,168.50
2 Tailgate centre logo	1	72.90	72.90
3 Tailgate weathestrip	1	408.90	408.90
4 Tailgate centre garnish	1	149.60	149.60
5 Tailgate lock	1	289.60	289.60
6 Tailgate inner trimboard	1	515.40	515.40
7 Taillamp assy - RH / LH	2	306.90	613.80
8 Taillamp lower garnish - LH	1	98.95	98.95
9 Rear end panel (inner)	1	1,105.95	1,105.95
10 Rear end panel (outer) <i>442.90</i>	1	442.90	442.90
11 Rear end panel top garnish	1	118.95	118.95
12 Rear bumper	1	399.65	399.65
13 Rear bumper side retainer -- LH	1	48.90	48.90
			6,434.00
		Less 25%	1,565.04
			4,868.96
SPECIAL NET			
14 Rear windscreen sealant	1	60.00	60.00
15 Tailgate '70km/h' sticker	1	25.00	25.00
16 Rear bumper sensor (set)	1	350.00	350.00
			435.00
LABOUR			
17 To remove and refit rear windscreen glass	1	150.00	150.00
18 To transfer damaged tailgate interior mechanism to new tailgate	1	120.00	120.00
19 To panel beat and straighten rear floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,500.00	1,500.00
20 To putty and spray paint on affected areas	1	1,000.00	1,000.00
21 To apply rust-proofing on replaced and repaired panels	1	160.00	160.00
22 To supply and paster logo on tailgate	1	680.00	680.00
			3,610.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Handwritten notes and corrections:

- 2168.50* (next to Tailgate)
- 204.45* (next to Tailgate centre logo)
- 50%* (next to Tailgate weathestrip)
- 442.90* (next to Rear end panel (outer))
- 405* (next to Rear windscreen sealant)
- 155* (next to Tailgate '70km/h' sticker)
- 200* (next to Rear bumper sensor (set))
- 120* (next to To remove and refit rear windscreen glass)
- 60* (next to To transfer damaged tailgate interior mechanism to new tailgate)
- 700* (next to To panel beat and straighten rear floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same)
- 500* (next to To putty and spray paint on affected areas)
- 60* (next to To apply rust-proofing on replaced and repaired panels)
- 400* (next to To supply and paster logo on tailgate)



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN :

YOUR REF NO : GBD2314L

CLAIM TYPE : THIRD PARTY

TP INS. CO. : LONPAC INSURANCE BHD

ACCIDENT DATE : 30/04/2022

TP VEH REG NO : GBD2314L

ESTIMATE

NO : QUOT202205-000044(00)

DATE : 18/05/2022

POLICY NO : 999995580

VEH REG NO : GBF5485X

MAKE/MODEL : TOYOTA HIACE VAN TURBO 5
DR

CHASSIS NO : JTFHT02P900209071

ENGINE NO : 1KD2660715

REG. DATE : 2016

Estimate Repair Cost to Vehicle No : GBF5485X

Description	Quantity	Unit Price	Amount
		S\$	S\$
		TOTAL	S\$ 8,913.96
		ADD GST @ 7%	623.98
		GRAND TOTAL	S\$ 9,537.94

SINGAPORE DOLLAR NINE THOUSAND FIVE HUNDRED THIRTY-SEVEN AND CENTS NINETY-FOUR ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE