

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/GRB22004672/VNY3E2

Date: 12/07/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : FBL9942K **Insured Vehicle No :** SLT4870G

Date of Loss: 12/05/2022 Nature of Claim: TP Claim No: MFL2022D0002456

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBL9942K**
Make & Model: HONDA CBF 190, 184cc Engine No: MC46E5035388
Reg. Date: 05/06/2017 (Man. Year: 2017) Chassis No: LWBMC4698H1111252
Colour: Black Odometer: 0 km
Engine Capacity: 184 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 140/70 R17 Rear Tyre Size: 140/70 R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 18/05/2022

Date Inspected: 19/05/2022 Inspected At: EQBH PTE LTD (HQ)
25 Kaki Bukit Road 4, #03-79, Synergy @ KB
Singapore 417800

Estimated Period of Repair: 0.0 days

Adjuster: Thevan Thomas Karthikesavan

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 12 Jul 2022)	
Parts:	N/A	HONDA CBF 190 184cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL9942K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >